

Dependent Resurvey of a Portion of the Subdivisional Lines,  
T. 5 S., R. 41 E., Willamette Meridian, Oregon

CHAINS									
	<p>Deposit a white "DEEP-1" magnetic marker at the base and set a 6 ft. steel fence post alongside the stainless steel post.</p> <p>The corner is located 0.450 chs. S. of a barbed wire fence extending E. and W.</p>								
67.50	<p>Ridge, slopes S. 30° E.; desc. SW. slope.</p>								
79.600	<p>The cor. of secs. 15, 16, 21, and 22.</p>								
	<p>From the cor. of secs. 10, 11, 14, and 15.</p> <p>N. 89° 58' 30" W., bet. secs. 10 and 15.</p> <p>Descend SW. slope, through medium timber and light undergrowth.</p>								
16.90	<p>Dirt road, 15 lks. wide, bears N. and S.</p>								
19.910	<p>Point for the E 1/16 sec. cor. of secs. 10 and 15.</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, and in a collar of stone, with brass cap mkd.</p> <div style="text-align: center;"> <table border="0"> <tr> <td></td> <td style="text-align: right;">S 10</td> </tr> <tr> <td style="text-align: right;">E 1/16</td> <td style="text-align: right;">—————</td> </tr> <tr> <td></td> <td style="text-align: right;">S 15</td> </tr> <tr> <td></td> <td style="text-align: right;">1990</td> </tr> </table> </div> <p>from which</p> <p style="padding-left: 40px;">A ponderosa pine, 12 ins. diam., bears S. 21° E., 37 lks. dist., mkd. E 1/16 S15 BT.</p> <p style="padding-left: 40px;">A ponderosa pine, 14 ins. diam., bears N. 87° W., 30 lks. dist., mkd. E 1/16 S10 BT.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.</p>		S 10	E 1/16	—————		S 15		1990
	S 10								
E 1/16	—————								
	S 15								
	1990								
	<p>Continue to desc. SW. slope.</p>								
30.30	<p>Graveled road, 20 lks. wide, bears N. 30° W. and S. 30° E.; desc. W. slope through logged area.</p>								
39.820	<p>The ¼ sec. cor. of secs. 10 and 15, monumented with the remains of the unmarked original stone, 11 x 6 x 3 ins. (record, 19 x 13 x 3 ins.), firmly set and broken at the center of the remains of a stone mound crushed by a bulldozer, from which the remains of the original bearing trees:</p>								
	<p>A burned pine snag, 20 ins. diam., bears N. 60° E., 15 lks. dist., no marks. (Record, 23 lks.)</p>								
	<p>The burned remains of a stump, size and species indeterminate, in a root hole, bears S. 50° W., 23 lks. dist., no marks. (Record, 15 lks.)</p>								
	<p>and bearing trees not of record</p>								

<b>UNION COUNTY SURVEYOR</b>	
Date Received	3/5/13
Date Filed	3/5/13
By	<i>JL G. Miller</i>
File No.	070-2013R