N	19	T55	RYIE
---	----	-----	------

Index File No.

R.

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUM	AENT SET OR WORK DONE TO PR	PESERVE FYISTING MONIMENT	
2½ /RON POST with 5' Steel F Deposit Original	28" Long S ence Post Ale	et 24"/11 ground	755 RHIE RRI 14 523 MK
ACCESSORIES DESCRIBE NEW BT	'S WITNESS OBJECTS ETC. ESTAE	LISHED, OR WORK DONE TO PRES	ERVE EXISTING EVIDENCE
A P. Pine 11"	BRS N103° F	43 LKS MKD	14 514 BT
A P. P. ine 16"	BRS S 5 1/2 E	334 LKS MK.	D 4 523 BT
	**		
Work Done By	Title	State Regist	
Certified Cor. Record Prepared ?	Yes No Filed At:		Date I
	REMARKS	S	

Tract or Surv. No.

UNION	COUNTY	
SURV	/EYOR	

Date Received

Date Filed 12 - 28 - 87

BY G. LANGLITZ, DEPUTY

File No. 429-871

12

Cor,

INDEX No. N-19

History of original corner establishment:

This corner was originally established by T5S R41E Henry M. Thatcher under GLO Contract No. 320, S14 dated April 1, 1879. The Surveyor General Record S23 1971

Set stone 21x7x7 for 1/4 Sec. Cor. Raised Stone (BLM Brass Cap) Mound at Cor.

In 1990 the Bureau of Land Management (BLM) conducted a dependent resurvey in T.5S., R.41E., W.M., under Group Nos. 1000 and 1484. This survey was executed by Philip G. Griffin, Cadastral Surveyor and commenced July 9, 1990 and was completed April 13, 1992. The following is the BLM's record for this corner:

In 1971 this corner was remonumented from original evidence by Steven D. Albright, BLM Cadastral Surveyor. In 1991 BLM Surveyor Griffin reports: The 1/4 sec. cor. of secs. 14 and 23, monumented with an iron post, 2% ins. diam., firmly set, projecting 3 ins. above ground, in a mound of stone, 2% ft. base, to top, with brass cap mkd. SEE DIAGRAM. From which bearing trees mkd. by Albright: A ponderosa pine, 15 ins. diam., bears N9°E., 42 lks. dist., with healed blaze. (Record: N10%°E, 43 lks). A ponderosa pine, 18 ins. diam., bears S9°E, 34 lks. dist., with healed blaze. (Record: S5%°E, 33% lks.).

Description of Corner Evidence Found:

Found a 2%" dia. iron post, extending 3" from the ground, with a brass cap marked as shown in diagram, surrounded by a mound of stone. Monument is solid and in good shape.

A Ponderosa Pine, 15" dia., with healed blaze, bears N9°E, 27.72 ft. (1971 Rec: N10%°E, 28.38 ft. 1991 Rec: same as I find)

A Ponderosa Pine, 18" dia., with healed blaze, bears S9°E, 22.44 ft. (1971 Rec: S5%°E, 22.11 ft. 1991 Rec: same as I find)

Description of monument and accessories I established to perpetuate the original location of this corner:

No work is needed on the monument. From Which:

Ponderosa Pine, 18" dia., bears S58°W, 25.5 ft., scribed: 1/4 S23 BT Douglas F12 18" dia., bears N76°W, 31.7 ft., scribed: 1/4 S14 BT

Measurements to BT's taken with magnetic compass, with the declination set at 20°E and chain. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs. Set 1/2" brass disc at base of blaze stamped: "L. Miller PLS 2513".

REGISTERED
PROFESSIONAL
LAND SURVEYOR

MAL
MIN 25, 1991
LINDA LEE MILLER
2513

MENOSA 12-31-94

This corner maintenance was performed by:
Linda Lee Miller, PLS 2513
May 21, 1995

Path Received Z-2-96

D-10 Filed 2-5-96

R. ROBINSON, DEPUTY

447

Dependent Resurvey of a Portion of the Subdivisional Lines, T. 5 S., R. 41 E., Willamette Meridian, Oregon

CHAI	INS
Chai	At the corner point
	Set a stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam, 22 ins. in the ground, and in a collar of stone, with brass cap mkd.
	T 5 S R 41 E S 15 S 14 S 22 S 23 1991
	from which new bearing trees
	A ponderosa pine, 18 ins. diam., bears N. 11° E., 29 lks. dist., mkd. TSS R41E S14 BT.
	A ponderosa pine, 18 ins. diam., bears S. 60° E., 92 lks. dist., mkd. T5S R41E S23 BT.
UNION COUNT SURVEYOR	A Douglas fir, 26 ins. diam., bears S. 9° W., 68 lks. dist., mkd. T5S R41E S22 BT.
Date Received 3/5/	A Douglas fir, 11 ins. diam., bears N. 87° W., 48 lks. dist., mkd. T5S R41E S15 BT.
Date Filed 3/5/	Deposit a white "DEEP-1" magnetic marker at the base and the corner stone alongside the stainless steel post.
By Mil Gille	From the cor. of secs. 13, 14, 23, and 24.
File No. 082-2	S. 89° 26' 00" W., bet. secs. 14 and 23.
georgesenen versen die George der George versen der George versen der George der George versen der Geo	Along S. slope changing to SE. slope.
35.7	5 Spin slopes &
39.7	The ¼ sec. cor. of secs. 14 and 23, monumented with an iron post, 2½ ins. diam., firmly set, projecting 3 ins. above ground, in a mound of stone, 2½ ft. base, to top, with brass cap mkd.
	T 5 S R 41 E S 14
	from which bearing trees mkd. by Albright
	A ponderosa pine, 15 ins. diam., bears N. 9° E., 42 lks. dist., with healed blaze. (Record, N. 10½° E., 43 lks.)
	A ponderosa pine, 18 ins. diam., bears S. 9° E., 34 lks. dist., with healed blaze. (Record, S. 5½° E., 33½ lks.)
	S. 89° 08' 30" W., beginning new measurement.
0.3	O Ravine, drains S. 30° E.; asc. E. slope.
4.5	O Spur, slopes SE.; continue along broken S. slope.

Remonumentation of Certain Original Corner Points, T. 5 S., R. 41 E., Willamette Meridian, Oregon

CHAINS

The $\frac{1}{4}$ sec. cor. of secs. 22 and 23, monumented with the original basalt stone, 17 x 9 x 7 ins., loosely set 5 ins. in the ground, with illegible chisel marks visible on N. face, from which the original bearing trees:

- A fir, 33 ins. diam., bears S. 71° E., 29 lks. \ dist., with scribe mark S visible on opened blaze.
- A root hole, bears S. 70° W., 31 lks. dist., with a down ponderosa pine alongside, 36 ins. diam., no marks visible.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.

T 5 S R 41 E 5 22 S 23 1971

from which new bearing trees

- A fir, 12 ins. diam., bears N. 62° E., 44 lks. dist., mkd. % S23 BT.
- A fir, 13 ins. diem., bears S. 20° W., 63 lks. dist., mkd. ½ S22 BT.

Deposit corner stone and set 5 ft. steel fence post alongside iron post.

The $\frac{1}{4}$ sec. cor. of secs. 14 and 23, monumented with the original basalt stone, 21 x 7 x 7 ins., firmly set 6 ins. in the ground, and in a mound of stone, 2 ft. base, to top, with illegible chisel marks visible on N. face.

At the corner point

Set an iron post, 28 ins. long, $2^{1}2$ ins. diam., 24 ins. in the ground, and in a mound of stone, 2 ft. base, to top, with brass cap mkd.

from which new bearing trees

- A ponderosa pine, 11 ins. diam., bears N. $10\frac{1}{2}^{\circ}$ E., 43 lks. dist., mkd. ½ S14 BT.
- A ponderosa pine, 16 ins. diam., bears S. $5\frac{1}{2}^{\circ}$ E., $33\frac{1}{2}$ 1ks. dist., mkd. $\frac{1}{4}$ S23 BT.

Deposit corner stone and set 5 ft. steel fence post alongside iron post.

The corner is located in old fence line, bears E. and W.

The ½ sec. cor. of secs. 21 and 28, monumented with the original basalt stone, 25 x 15 x 9 ins., firmly set 14 ins. in the ground, with illegible chisel marks visible on N. face, and in a mound of stone, 2 ft. base, to top.

UNION COUNTY SURVEYOR

Date Received

Date Heceived

Date Filed

File No.