

Dependent Resurvey of a Portion of the Subdivisional Lines,  
T. 5 S., R. 41 E., Willamette Meridian, Oregon

CHAINS	
	From this point, a ponderosa pine, 33 ins. diam., bears N. 63° 47' E., 2.850 chs. dist., with circular and straight scribe marks visible on opened blazes on the E. and W. sides. This tree mkd. by person(s) unknown.
	From the cor. of secs. 13 and 24 only, on the E. bdy. of the Tp. S. 89° 41' 30" W., bet. secs. 13 and 24. Along N. slope, through moderate timber and light undergrowth.
1.50	Ravine, drains N.; asc. NE. slope.
7.70	Abandoned road, 20 lks. wide, bears N. 20° W. and S. 20° E.
15.00	North edge of rounded butte; desc. NW. slope changing to broken W. slope.
38.300	<p>Point for the ¼ sec. cor. of secs. 13 and 24, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd.</p> <p style="text-align: center;">T 5 S R 41 E S 13 ¼ ——— S 24 1991</p> <p>from which</p> <p style="padding-left: 40px;">A larch, 13 ins. diam., bears S. 42° W., 61 lks. dist., mkd. ¼ S24 BT.</p> <p style="padding-left: 40px;">A ponderosa pine, 17 ins. diam., bears N. 7° W., 57 lks. dist., mkd. ¼ S13 BT.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.</p>
55.60	<del>Spur, slopes N. 60° W., desc. steep W. slope</del>
57.450	<p>Point for the W 1/16 sec. cor. of secs. 13 and 24.</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, and in a collar of stone, with brass cap mkd.</p> <p style="text-align: center;">S 13 W 1/16 ——— S 24 1991</p> <p>from which</p> <p style="padding-left: 40px;">A ponderosa pine, 13 ins. diam., bears N. 75½° E., 61 lks. dist., mkd. W 1/16 S13 BT.</p>

<b>UNION COUNTY SURVEYOR</b>	
Date Received	3/5/13
Date Filed	3/5/13
By	<i>[Signature]</i>
File No.	085-2013R