CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established.

T5S R41E P-14

DESCRIPTION OF CORNER EVIDENCE FOUND:

None

S 22

See Minor Partition Number 20100001T

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron rod with 2 ½" Aluminum Cap marked as shown, 29 ins. in the ground, from which:

BEARING TREES:

- A 14 in. Western Larch bears North 79° East, a distance of 52.66 feet, marked CW 1/16 S22 BT.
- A 9 in. Douglas Fir bears South 3° East, a distance of 30.07 feet, marked CW 1/16 S22 BT.
- I hereby certify that the corner was set on December 2, 2009.

Set a steel fencepost 1 ft. South of corner monument.

Witness: Jeff Hsu, Gregory T. Blackman, Jr.

REGISTERED **PROFESSIONAL** LAND SURVEYOR OREGON

RICK G. ROBINSON 2219

Renewal Date: December 31, 2010

GRIFFITH T5S R41E W 1/16 C S 22 2009 2219 **OPLS**

UNION COUNTY **SURVEYOR**

2/2/2010

219/2010

I used a steel tape and magnetic compass in the establishment of the accessories. I used 18° East declination, the distances are to a 60d spike driven into the root crown at the right side of the bearing trees. Attached brass washer marked OPLS 2219 to BT blaze.