## **ATIFIED RECORD OF LAND CORNER MONUMENTATION**

## HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established.

T5S R41E P-16



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Survey Number 035-2012

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

## TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron rod with 2 ½" Aluminum Cap marked as shown, 25 ins. in the ground, in a collar of stone 1 ½ ft. diam., from which:

## BEARING TREES:

A 16 in. Ponderosa Pine bears North 60° East, a distance of 70.40 feet, marked CE 1/16 S22 BT.

a 6 in. Douglas Fir bears South  $16^{\circ}$  East, a distance of 14.15 feet, marked CE 1/16 S22 BT.

I hereby certify that the corner was set on October 23, 2012.

I set a steel fencepost 1 foot Northwest of the corner monument.

REGISTERED PROFESSIONAL LAND SURVEYOR

June 2, 2010 JEFFERY S. HSU 83571

DREGON

Renewal Date: June 30, 2013

GRIFFITH & SLACE TO SEE 1/16

C S 22

2012

OPLS 83571

UNION COUNTY SURVEYOR

Date Received

File Number 672-2012 R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 16° East declination, the distances are to a 60d spike driven into the root crown at the right side of the bearing trees. Attached brass washer marked OPLS 83571 to BT blaze.