

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. P-21

History of original corner establishment:

This corner was originally established by Henry M. Thatcher under GLO Contract No. 320, dated April 1, 1879. The Surveyor General Record states:

DIAGRAM  
T5S R41E  
1/4  
S23|S24  
1991  
(BLM Brass Cap)

Set stone 12x10x6 for 1/4 Sec. Cor. Raised Stone Mound at Cor.

In 1990 the Bureau of Land Management (BLM) conducted a dependent resurvey in T.5S., R.41E., W.M., under Group Nos. 1000 and 1484. This survey was executed by Philip G. Griffin, Cadastral Surveyor and commenced July 9, 1990 and was completed April 13, 1992. The following is the BLM's record for this corner:

The 1/4 sec. cor. of secs. 23 and 24, monumented with the original basalt stone, 12x9x6 ins. (record 12x10x6 ins.), firmly set at the center of an embedded collar of stone, with illegible chisel marks, at the corner point set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, and in a collar of stone, with brass cap marked, SEE DIAGRAM, from which new bearing trees: A ponderosa pine, 18 ins. diam., bears N72 1/2°E, 88 lks. dist., mkd. 1/4 S24 BT. A ponderosa pine, 20 ins. diam., bears S16°W, 91 lks. dist., mkd. 1/4 S23 BT. Deposit a white "DEEP-1" magnetic marker at the base and the corner stone alongside the stainless steel post.

Description of Corner Evidence Found:

Found a 2 1/2" dia. stainless steel post with brass cap marked as shown in diagram, extending 6" from the ground, in a mound of stone. Monument is solid and in good condition.

A Ponderosa Pine, 18" dia., with scribing visible, bears N72 1/2°E, 58.08 ft. (Established by BLM)

A Ponderosa Pine, 20" dia., with scribing visible, bears S16°W, 60.06 ft. (Established by BLM)

Description of monument and accessories I established to perpetuate the original location of this corner:

No work is needed on the monument.  
From Which:

Ponderosa Pine, 11" dia., bears S60°E, 11.2 ft., scribed: 1/4 S24 BT  
Ponderosa Pine, 6" dia., bears N35°W, 24.2 ft., scribed: X BT

Measurements to BT's taken with magnetic compass, with the declination set at 20°E and chain. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs. Set 1/2" brass disc at base of blaze stamped: "L. Miller PLS 2513".



Renewed 12-31-96

This corner maintenance was performed by:  
Linda Lee Miller, PLS 2513  
May 21, 1995

NEVON COUNTY REGISTER  
Date Received 2-2-96  
Date Filed 2-5-96  
R. ROBINSON, Deputy  
File No. 028-1996R


Office of \_\_\_\_\_ County of \_\_\_\_\_  
State of \_\_\_\_\_ I hereby certify that the within instrument was  
filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_  
by \_\_\_\_\_ (COUNTY OFFICIAL) \_\_\_\_\_ (DEPUTY)

**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**HISTORY OF ORIGINAL CORNER ESTABLISHMENT:**

Corner originally established by H.M. Thatcher under GLO Contract Number 320, dated April 1, 1879. Surveyor General record states:  
Set stone 12x10x6 for 1/4 Sec. Cor. Raised stone mound at cor.

T 5 S R 41 E P-21



Corner reestablished by BLM Cadastral Surveyor Phillip Griffin in BLM dependent resurvey under Group Numbers 1000 and 1484, dated July 13, 1979 and June 26, 1990. BLM field notes state:

The 1/4 sec. cor. of secs. 23 and 24, monumented with the original basalt stone, 12x9x6, firmly set at the center of a embedded collar of stone, with illegible chisel marks.  
Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with brass cap mkd., from which new bearing trees

A ponderosa pine, 18 ins. diam., bears N. 72 1/2° E., 88 lks. dist., mkd. 1/4 S24 BT.  
A ponderosa pine, 20 ins. diam., bears S. 16° W., 91 lks. dist., mkd. 1/4 S23 BT.

Corner found by Linda Lee Miller in Survey Number 006-1996. Union County Monumentation record 028-1996R states:

Found 2 1/2" dia. stainless steel post with brass cap marked as shown, extending 6" from the ground in a mound of stone. Monument is solid and in good condition.

A Ponderosa Pine, 18" dia., bears N 72 1/2°E, 58.08 ft. (established by BLM)

A Ponderosa Pine, 20" dia., bears S 16° W, 60.06 ft. (established by BLM)

New trees:

Ponderosa Pine, 11" dia., bears S60°E, 11.2 ft., scribed 1/4 S24 BT.

Ponderosa Pine, 6" dia., bears N35°W, 24.2 ft., scribed X BT.

**DESCRIPTION OF CORNER EVIDENCE FOUND:**

Found 2 1/2" iron pipe with 3" brass cap marked as shown below, 3 inches above ground in a collar of stone 2 ft. diam., from which:

- A 20 inch Ponderosa Pine bears North 79° East, a distance of 58.80 feet, alive and vigorous with a healed blaze.
- A 14 inch Douglas fir bears South 28° East, a distance of 7.55 feet, alive and vigorous with a healed blaze.
- A 22 inch Ponderosa Pine bears South 16° West, a distance of 65.05 feet, alive and vigorous with a healed blaze.
- A 10 inch Ponderosa Pine bears North 32° West, a distance of 36.40 feet, alive and vigorous with healed blaze.

See Survey Number 035-2012

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED**


**TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:**

I hereby certify that the corner was perpetuated on October 22, 2012.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
June 2, 2010  
JEFFERY S. HSU  
83571

Renewal Date: June 30, 2013



**UNION COUNTY  
SURVEYOR**  
Date Received 11/5/12  
Date Filed 11/5/12  
Filed By R. Robinson Deputy  
File Number 073-2012R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 16° East declination, the distances are to a 60d spike driven into the root crown at the right side of the bearing trees. Attached brass washer marked OPLS 83571 to BT blaze.

435

Dependent Resurvey of a Portion of the Subdivisional Lines,  
T. 5 S., R. 41 E., Willamette Meridian, Oregon

CHAINS	
	<p>A ponderosa pine, 17 ins. diam., bears N. 30° W., 21 lks. dist., mkd. W 1/16 S24 BT.</p> <p>The corner is located on top of a bedrock outcropping, 7 ft. x 4 ft. x 2 ft. above ground.</p>
25.50	Ravine, drains S.
30.50	Spur, slopes S.
39.020	The cor. of secs. 23, 24, 25, and 26.
	<hr/> <p>N. 0° 12' 30" E., bet. secs. 23 and 24. Over broken W. slope through logged area.</p>
14.00	Descend N. slope.
16.50	Descend steep NE. slope.
20.205	Point for the S 1/16 sec. cor. of secs. 23 and 24.
	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, and in a collar of stone, with brass cap mkd.
	<p style="text-align: center;">S 1/16 S 23   S 24 1991</p>
	from which
	A lodgepole pine, 10 ins. diam., bears N. 52¾° E., 94 lks. dist., mkd. S 1/16 S24 BT.
	A ponderosa pine, 20 ins. diam., bears N. 89° W., 75 lks. dist., mkd. S 1/16 S23 BT.
	Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.
	Continue to descend steep broken NE. slope, through moderate timber and light undergrowth.
40.410	<p>The ¼ sec. cor. of secs. 23 and 24, monumented with the original basalt stone, 12 x 9 x 6 ins. (record, 12 x 10 x 6 ins.), firmly set at the center of an embedded collar of stone, with illegible chisel marks.</p> <p>At the corner point</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, and in a collar of stone, with brass cap mkd.</p> <p style="text-align: center;">T 5 S R 41 E S 23   S 24 1991</p> <p>from which new bearing trees</p>

UNION COUNTY  
SURVEYOR

Date Received 3/5/13

Date Filed 3/5/13

By *H. G. Miller*

File No. 093-2013R

436

Dependent Resurvey of a Portion of the Subdivisional Lines,  
T. 5 S., R. 41 E., Willamette Meridian, Oregon

CHAINS									
	<p>A ponderosa pine, 18 ins. diam., bears N. 72½° E., 88 lks. dist., mkd. ¼ S24 BT.</p> <p>A ponderosa pine, 20 ins. diam., bears S. 16° W., 91 lks. dist., mkd. ¼ S23 BT.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base and the corner stone alongside the stainless steel post.</p>								
35.65	<p>N. 1° 45' 00" E., beginning new measurement.</p> <p>Descend steep, broken NE. slope to South Fork of Catherine Creek; thence over spur.</p> <p>North Fork of Catherine Creek, 100 lks. wide, course S. 70° W.; continue over creek bottom land.</p>								
37.55	<p>Graveled road, 25 lks. wide, bears N. 80° E. and S. 70° W.; asc. S. slope.</p>								
39.540	<p>The cor. of secs. 13, 14, 23, and 24, monumented with the original basalt stone, 14 x 12 x 6 ins., loosely set 3 ins. in the ground, with no clear marks. (Loose alongside find an ancient broken wood signboard predating 1953 by its designation of this place as the boundary of the Whitman National Forest.)</p> <p>At the corner point</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd.</p> <div style="text-align: center;"> <table border="1"> <tr> <td>T 5 S</td> <td>R 41 E</td> </tr> <tr> <td>S 14</td> <td>S 13</td> </tr> <tr> <td>S 23</td> <td>S 24</td> </tr> <tr> <td colspan="2">1991</td> </tr> </table> </div> <p>from which new bearing trees</p>	T 5 S	R 41 E	S 14	S 13	S 23	S 24	1991	
T 5 S	R 41 E								
S 14	S 13								
S 23	S 24								
1991									
	<p>A Douglas fir, 16 ins. diam., bears N. 86½° E., 62 lks. dist., mkd. T5S R41E S13 BT.</p>								
	<p>A Douglas fir, 22 ins. diam., bears S. 3° E., 89 lks. dist., mkd. T5S R41E S24 BT.</p>								
	<p>A ponderosa pine, 16 ins. diam., bears S. 45° W., 68 lks. dist., mkd. T5S R41E S23 BT.</p>								
	<p>A Douglas fir, 30 ins. diam., bears N. 89° W., 179 lks. dist., mkd. T5S R41E S14 BT.</p>								
	<p>Deposit a white "DEEP-1" magnetic marker at the base and the corner stone alongside the stainless steel post.</p>								
	<p>Raise a mound of stone, 4 ft. base, 1½ ft. high, W. of the corner.</p>								

UNION COUNTY  
SURVEYOR

Date Received

3/5/13

Date Filed

3/5/13

File No.

093-2013R