


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Not previously established

T 5 S R 41 E S-01



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

SEE SURVEY NUMBER 041-2017

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8"x30" iron pin, 21" in the ground with 2 1/2" aluminum cap marked as shown below, in mound of stone 3 ft. base to top of cap:

From which:

An 11" White Fir bears North 30° East a dist. of 24.45 ft. marked N1/16S30 BT
A 15" White fir bears North 18° West a dist. of 41.85 ft. marked N1/16S25 BT

Set a steel fence post approx. 2 ft. North. An ancient fence corner bears East approx. 5 ft.

I hereby certify that the corner was monumented October 13, 2017.

Witness: Kyle Tucker

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**




OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2019

**UNION COUNTY
SURVEYOR**

Date Received 10/24/17

Date Filed 10/24/17

Filed By 

File Number 044-2017R

I used a steel tape and magnetic compass in the establishment of the bearing tree. Magnetic declination used was 13° East. Bearing is to a brass washer marked OPLS 83571 in the lower blaze of the tree. Distance is to a spike set in the root crown of the side of the tree.