


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Not previously established

T 5 S R 41 E S-04



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

SEE SURVEY NUMBER 041-2017

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey set a 5/8"x30" iron pin, 27" in the ground, with 2 1/2" aluminum cap marked as shown below:

From which:

An 11" spruce bears North 62° East, a distance of 9.00 feet, marked NE 1/16 S30 BT.
A 7" spruce bears South 41° East, a distance of 5.65 feet, marked NE 1/16 S30 BT.

Set a steel fence post approx. 1 ft. North.

I hereby certify that the corner was monumented October 18, 2017.

Witness: Kyle Tucker

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2019

BAGETT - GRIFFITH & BLACKMAN

T5S R41E

NE 1/16 S30

2017
OPLS 83571

**UNION COUNTY
SURVEYOR**

Date Received 10/24/17

Date Filed 10/24/17

Filed By [Signature]

File Number 040-2017R

I used a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 13° East. Bearing is to a brass washer marked OPLS 83571 in the lower blaze of the tree. Distance is to a spike set in the root crown of the side of the tree.