
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Not previously established

T5S R41 ET-04



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

SEE SURVEY NUMBER 041-2017

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey set a 5/8"x30" iron pin, 28" in the ground, with 2 ½" aluminum cap marked as shown below:

From which:

A 7" Douglas Fir bears East, a distance of 7.10 feet, marked CE 1/16 S30 BT. A 13" Douglas Fir bears North 5° West, a distance of 14.55 feet, marked CE 1/16 S30 BT.

Set a steel fence post approx. 1 ft. North.


I hereby certify that the corner was monumented October 18, 2017.

Witness: Kyle Tucker

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2019



UNION COUNTY
SURVEYOR

Date Received 10/24/17

Date Filed 10/24/17

Filed By 1/4/6/11

File Number 042-2017 R

I used a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 13° East. Bearing is to a brass washer marked OPLS 83571 in the lower blaze of the tree. Distance is to a spike set in the root crown of the side of the tree.