

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

40.29 Point for the $\frac{1}{4}$ sec. cor. of secs. 27 and 28, at proportionate distances; there is no remaining evidence of the original corner. Set a stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 28 ins. in the ground, with top flush with the surface, with brass cap, from which:

- A ponderosa pine, 16 ins. diam., bears N.82 $\frac{1}{2}$ °E., 85 lks. dist. mkd. $\frac{1}{4}$ S27 BT
- A larch, 15 ins. diam., bears N.44°W., 26 lks. dist. mkd. $\frac{1}{4}$ S28 BT.

Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

The corner is located in the northerly edge of an abandoned dirt road, 20 lks. wide, bearing E, and W.


Description of corner evidence found:

Found a $2\frac{1}{2}$ " B.L.M. brass cap, level with road from which:

- A tamarack, 14" diam., bears N43.00°W., 17.23', with a 1' x 14" blaze (not legible).
- A pine, 15" diam., bears N.82°27'E., 56.02', with a 1' x 4" blaze (not legible).

Description of monument and accessories I established to perpetuate the original location of this corner:

- A fir, 10" diam., bears S.08°26'E., 55.74', scribed " $\frac{1}{4}$ S27BT".
- A fir, 17" diam., bears S.36°55'W., 23.76', scribed " $\frac{1}{4}$ S28BT".



UNION COUNTY SURVEYOR	
Date Received	<u>10/18/84</u>
Date Filed	<u>10/23/84</u>
By	<u>[Signature]</u>
File No.	<u>110-1994R</u>

REGISTERED PROFESSIONAL LAND SURVEYOR
<u>[Signature]</u> 10/94
OREGON JULY 15 1983 RONALD E. STOLL 2058

Office of _____ County of _____
State of _____ I hereby certify that the within instrument was filed in this office
for record on the ____ day of _____, 19____
_____ by _____
(COUNTY OFFICIAL) (DEPUTY)

0

T-13

457

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 5 S., R. 41 E., Willamette Meridian, Oregon

CHAINS	<p>A ponderosa pine, 22 ins. diam., bears S. 59° W., 79 lks. dist., mkd. W 1/16 S34 BT.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.</p> <p>Continue to ascend steep SE. slope.</p> <p>60.50 Dirt road, 20 lks. wide, bears NE. and SW.</p> <p>70.00 Broad ridge, bears NE. and SW.; desc. NW. slope.</p> <p>79.060 The cor. of secs. 27, 28, 33, and 34.</p>
--------	---

N. 0° 09' 30" E., bet. secs. 27 and 28.

Descend steep NW. slope through medium timber and light
undergrowth.

40.000	<p>Point for the 1/4 sec. cor. of secs. 27 and 28, at proportionate distance; there is no remaining evidence of the original corner.</p>
--------	--

Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 28 ins.
in the ground, with top flush with the surface, with brass cap
mkd.

T 5 S R 41 E
S 28 | S 27
1991

from which

A ponderosa pine, 16 ins. diam., bears N. 82 1/4° E.,
85 lks. dist., mkd. 1/4 S27 BT.

A larch, 15 ins. diam., bears N. 44° W., 26 lks. dist.,
mkd. 1/4 S28 BT.

Deposit a white "DEEP-1" magnetic marker at the base of the
stainless steel post.

The corner is located in the northerly edge of an abandoned dirt
road, 20 lks. wide, bearing E. and W.

42.20	Graveled road, 35 lks. wide, bears N. 75° E. and S. 15° W.
-------	--

60.000	Point for the N 1/16 sec. cor. of secs. 27 and 28.
--------	--

Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 22 ins.
in the ground, with brass cap mkd.

N 1/16
S 28 | S 27
1991

from which

UNION COUNTY
SURVEYOR

Date Received 3/5/13

Date Filed 3/5/13

By [Signature]

File No. 126-2013R