
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT: None

No record of subsequent monumentation found in Union County survey records



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Survey Number 035-1998

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey I set a $2\frac{1}{2}$ "x 30" aluminum pipe with aluminum cap marked as shown, 28 inches in the ground, from which;

NEW BEARING TREES:

A 10" Douglas Fir bears N 50 $^\circ$ E, a distance of 30.73 feet, marked CS 1/16 S30

A 7" Douglas Fir bears S 33 $^{\circ}$ E, a distance of 49.40 feet, marked CS 1/16 S30 BT.


I hereby certify that the corner was monumented on September 15, 1998 Witness: Norbert Volny and Greg Engelgau

> REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON

RICK G. ROBINSON 2219

Renewal Date December 31, 1998



I used a steel tape and compass with 17° $\rm E$ magnetic declination in the establishment of the new accessories. The distances are to a 60d spike driven into the right side of the root crown of the bearing tree. I attached a brass washer marked OPLS 2219 to the BT blaze.

UNION COUNTY SURVEYO 076-1998 R