

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 5 S., R. 41 E., Willamette Meridian, Oregon

CHAINS	
	From the cor. of secs. 25, 26, 35, and 36.
	N. 89° 57' 00" W., bet. secs. 26 and 35.
	Ascend gradually over NE. slope, through medium timber and light undergrowth.
6.00	Descend NW. slope.
30.00	Graveled road, 35 lks. wide, bears irregularly N. and S.
38.40	Stream, 5 lks. wide, course N.
40.300	Point for the $\frac{1}{4}$ sec. cor. of secs. 26 and 35, at proportionate distance; the true corner point cannot be determined from the remains of the original evidence, the original unmarked slate stone, 15 x 11 x 5 ins., buried, displaced, and broken into two pieces.
	At the corner point
	Set a stainless steel post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 28 ins. in the ground, the top flush with the surface, with brass cap mkd.
	T 5 S R 41 E S 26 $\frac{1}{4}$ ————— S 35 1991
	from which new bearing trees
	A spruce, 23 ins. diam., bears N. 23 $\frac{1}{2}$ ° E., 126 lks. dist., mkd. $\frac{1}{4}$ S26 BT.
	A larch, 14 ins. diam., bears S. 81° E., 32 lks. dist., mkd. $\frac{1}{4}$ S35 BT.
	Deposit a white "DEEP-1" magnetic marker at the base and the original corner stone alongside the stainless steel post.
	The corner is located in the center of an abandoned road, 15 lks. wide, bears NE. and SW., in a curve.
	Ascend broken SE. slope through logged area.
65.00	Broad spur, slopes N.; continue over broken land.
80.600	The cor. of secs. 26, 27, 34, and 35.
	N. 1° 11' 30" E., bet. secs. 26 and 27.
	Along gradual W. slope, through medium timber and light undergrowth.
	Point for the $\frac{1}{4}$ sec. cor. of secs. 26 and 27, at proportionate distance; there is no remaining evidence of the original corner.

UNION COUNTY
SURVEYOR

Date Received 40.350
3/5/13

Date Filed 3/5/13

By [Signature]

File No. 145-2013