

105-69A

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:


Original survey by General Land Office contract survey;

The original notes state;

A western larch 8" in diam bears N2°E 18 lks dist marked T5S R41E S25BT;

A 8" black pine bears N70°W 25 lks dist marked T5S R41E S26BT;


A fir 25" in diam bears S30°W 32 lks dist marked T5S R41E S35BT/



Description of corner evidence found:

Found a 22" tamarack at N2°E 18 lks dist with blaze scar.


Found a 10" black pine at N70°W 25 lks dist marked T5S R41E S26BT; (now dead)



Description of monument and accessories I established to perpetuate the original location of this corner

At the position of the corner I set a 2" galvanized pipe 30" long with a bronze cap on top and a 8" plate welded to bottom. The pipe set to a depth of 22" and back filled with stone and tamped soil.

I stamped the disk.



From the monument the original bearing trees are;

A tamarack 22" in diam bears N2° E 18 lks dist.

I set the following new bearing trees.

A tamarack 10" in diam bears N85°W 63 ft. dist marked T5S R41E S26BT;

A fir 11" in diam bears S34°W 26.5 ft. dist marked T5S R41E S35BT;

A fir 12" in diam bears S23°E 38.3 ft. dist marked T5S R41E S36BT;

(distance measured to center of trees and marked with a scribe.)

A USFS sign 54-4 was placed at the corner and USFS bearing trees signs were placed on the bearing trees facing the corner.

Office of.....County surveyor..... County of..... Union.....

State of.....Oregon....., I hereby certify that the within instrument was filed in this office for record on the 8 day of Oct 1969 at 9 o'clock P.m. (signed)

.....County Surveyor..... by *James G. Voelz* (DEPUTY)

UNION COUNTY
SURVEYOR

Date Received _____

Date Filed _____

By _____

File No. 725-84 R

430

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 5 S., R. 41 E., Willamette Meridian, Oregon

CHAINS	
	(Restoring the survey by Henry M. Thatcher, in 1879, and the remonumentation by Steven D. Albright, in 1971)
	From the standard cor. of secs. 35 and 36 on the S. bdy. of the Tp.
	N. 0° 38' 00" E., bet. secs. 35 and 36.
	Ascend SW. slope.
4.00	Spur, slopes N. 60° W.
24.30	Graveled road, 25 lks. wide, bears N. 70° E. and S. 70° W., on ridge bearing the same.
35.50	Ravine, drains W.; asc. S. slope.
40.560	Point for the ¼ sec. cor. of secs. 35 and 36 at proportionate distance; there is no remaining evidence of the original corner.
	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.
	T 5 S R 41 E S 35 S 36 1991
	from which
	A fir, 26 ins. diam., bears N. 85½° E., 71 lks. dist., mkd. ¼ S36 BT.
	A larch, 15 ins. diam., bears N. 80¼° W., 72 lks. dist., mkd. ¼ S35 BT.
	Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.
	Ascend SW. slope.
74.00	Descend NE. slope.
81.120	The cor. of secs. 25, 26, 35, and 36, perpetuated and recorded by James G. Voelz, Registered Land Surveyor No. 381, in 1969, recorded under file No. 725-84R, monumented with an iron pipe, 2½ ins. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd.
	COR T 5 S R 41 E S 26 S 25 S 35 S 36 ORE LIC 381 1969
	from which the remains of the original bearing trees

**UNION COUNTY
SURVEYOR**

Date Received 3/5/13

Date Filed 3/5/13

By [Signature]

File No. 146-2013R

431

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 5 S., R. 41 E., Willamette Meridian, Oregon

CHAINS	
	<p>A larch, 25 ins. diam., bears N. 10° E., 19½ lks. dist., with healed blaze. (Record, N. 2° E., 18 lks.)</p> <p>A root hole, bears N. 60° W., 25 lks. dist., with lodgepole pine log alongside, 13 ins. diam., with fragmentary scribe marks visible on opened blaze. (Record, N. 70° W.)</p> <p>and bearing trees mkd. by Voelz</p> <p>A fir, 18 ins. diam., bears S. 27¾° E., 57 lks. dist., with healed double blaze.</p> <p>A fir, 15 ins. diam., bears S. 28¾° W., 40 lks. dist., with healed double blaze.</p> <p>A larch, 15 ins. diam., bears S. 89½° W., 95 lks. dist., with healed double blaze.</p> <p>No suitable trees available in sec. 26.</p>
<p>3.00</p> <p>10.00</p> <p>39.205</p>	<p>From the cor. of secs. 25 and 36, on the E. bdy. of the Tp. N. 89° 34' 00" W., bet. secs. 25 and 36.</p> <p>Descend W. slope.</p> <p>Ravine, drains N. 30° E.; asc. E. slope.</p> <p>Spur, slopes N.</p> <p>Point for the ¼ sec. cor. of secs. 25 and 36, at proportionate distance; there is no remaining evidence of the original corner.</p>
<p>UNION COUNTY SURVEYOR</p> <p>Date Received 3/5/13</p> <p>Date Filed 3/5/13</p> <p>By <i>R.L. G. [Signature]</i></p> <p>File No. 146-2013E</p>	<p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T 5 S R 41 E S 25 ¼ S 36 1991</p> <p>from which</p> <p>A lodgepole pine, 12 ins. diam., bears N. 32° E., 16 lks. dist., mkd. ¼ S25 BT.</p> <p>A larch, 17 ins. diam., bears S. 57° W., 63 lks. dist., mkd. ¼ S36 BT.</p>
<p>42.00</p> <p>47.25</p> <p>51.50</p>	<p>Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.</p> <p>Ridge, bears N. and S.; desc. W. slope.</p> <p>Graveled road, 20 lks. wide, bears N. and S.</p> <p>Ascend over gradual NE. slope.</p>