CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Original survey by Henry W. Thatcher under Contract No. 320, April 1, 1879.

Set stone 12x10x6 ins. for corner to townships 4 and 5 South, Ranges 41 and 42 East, W.M., Oregon. Raised stone mound at corner, from which, a Fir 34 in. diam. bears N 80°W 18 lks. distant.

DIAGRA	1	
R41E	R42E	
S36	S31	
S1	S6	
T5S		
PLS 1099		
19	83	

Description of corner evidence found:

Found a Basalt Stone 15"x12"x10" with chiseled markings:

6 Notches on South Edge

6 Notches on North Edge

"42" on East Face and "4" on West Face in a mound of stone 2 1/2 ft. diameter and 1 ft. high. At record bearing and distance from found stone for original bearing tree, we find rotted Douglas Fir bark and wood in ground.

Description of monument and accessories I established to perpetuate the original location of this corner:

nized iron pipe, 28	B" in the ground wi	f the found corner stone, we s th brass cap attached, <u>marked</u> : south side of brass cap	set a 2"x30" galva- T4S R41E R42E
from which we mark	the following RT's	•	\$36 \$31
A 12" Douglas F	ir, scribed "T4S R	42E S31 BT" on a Double	S1 S6
	58 1/2°E 7.2 ft.	415 006 078	T5S
		41E S36 BT" on a Double	PLS 1099
	1 74°W 33.6 ft.		1983
A 16" White Fir	', scribed "T5S R41	E S1 BT" on a Double blaze	
bears S 65°W	47.4 ft.		
and a 20" Dougl	as Fir. scribed "T	5S R42E S6 BT" on a Double	
	S85°E 44.1 ft.	oo kill oo bi on a boubic	
		" to lower blaze of new BT's.	
Bearing and horizon	ital distance measu	red to center of bearing tree	at ground level.
Staff Compass (21°	East Declination)	Steel Tape	
Oct. 13, 1983	Witnesses:	Gary Langlitz LS 1099 Dave Dahlstrom, U.S.F.S.	FROFESSIONAL

LAND SURVEYOR

Office of	County of	
State of, / hereby certify to	hat the within instrument was filed in this of it	" UNION COUNTY
for record on the day of	, 19	SURVEYOR
by		
(COUNTY OFFICIAL)	(DEPUTY)	Data Received 11-10-83

Form R6-7100-57 (9/71)