

Form 874-9  
 U. S. DEPARTMENT OF AGRICULTURE  
 FOREST SERVICE

Whitman NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 5-S. R. 4-14-E Will Mer.

1/4 Corner common to Sections  
7, and 12

DESCRIPTION OF CORNER

Corner consists of a Destroyed

Dimension above ground \_\_\_\_\_ inches.  
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION				DIAGONAL POSITION			
N	W	S	E	NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

			<u>1/2 S</u> <u>Sec 7</u>
			<u>BT</u>

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

John R. Mitchell  
 Signature

6-9-41  
 Date

Guard  
 Title

USDA-FOREST SERVICE GPO 940-117  
 Index File No. G-1  
 T. 5-S. R. 4-14-E N.F. 2-20  
 Merid. \_\_\_\_\_ State \_\_\_\_\_  
 CORNER RECORD (SEARCH) (Ref. FSM 7151.4)  
 Tract or Survey No. \_\_\_\_\_  
 COR. NO. \_\_\_\_\_  
 Increase in CORNER MONUMENT FOUND

00-52 (3/68)

ACH CORNER

**UNION COUNTY SURVEYOR**

Date Received \_\_\_\_\_

Date Filed 12-28-87

By G. LANGLITZ, DEPUTY

File No. 449-87R

G-1