

U. S. Department of Agriculture  
FOREST SERVICE

*X-5 Whitman* NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY  
T. *5S* R. *R42E* W. *1* Mer.

*1/4* Corner common to Sections  
*31* and *32*  
Corner consists of a *Wooden post* (not) in place  
State condition *Very decayed*

Dimensions above ground \_\_\_\_\_ inches.  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION				DIAGONAL POSITION			
N	W	S	E	NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>Marks chopped tree decayed</i>					
Species <i>D. fir</i>					
Diameter <i>25</i>					
Bearing <i>S25°W</i>					
Distance <i>7.1 links</i>					

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? \_\_\_\_\_

*J. S. Kampman*  
(Signature)  
*9/9/42*  
(Date)  
*J. S. Kampman*  
(Title)

ACH CORNER

USDA-FOREST SERVICE GPO 940-117  
Index File No. *X-5*  
T. *5S* R. *42E* W. *1*  
Merid. \_\_\_\_\_  
CORNER POSITION \_\_\_\_\_  
N. F. *W-W*  
CORNER RECORD (SEARCH) (Ref. FSM 7151.4)  
County *Union* State *OR*  
Tract or Survey No. \_\_\_\_\_  
Cor. No. \_\_\_\_\_

Signature *Kampman*  
Title \_\_\_\_\_  
Division \_\_\_\_\_  
Headquarters \_\_\_\_\_  
Date *9-9-42*  
7100-52 (3/68)

UNION COUNTY SURVEYOR  
Date Received \_\_\_\_\_  
Date Filed *12-28-87*  
By *G. LANGLITZ, DEPUTY*  
File No. *465-87R*

X-5