CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: The original subdivision of T6S R35 1/2E was by E. McCornack under Contract No. 398, approved January 9, 1883. Set a post and 18x18x12 pitse. east and west of post 5.5 ft. and raised a mound of earth 1 1/2 ft. high and 3.5 ft. across the base around the post.

Index File No. C-09 DIAGRAM T6S R35E | R35 1/2E 1/4 S4

Description of corner evidence found:

No corner monument or other official accessories found.

Description of monument and accessories I established to perpetuate the original location of this corner: Corner set by proportion. Cap is stamped: Set 2.5" aluminum cap on 2 3/8"x30" aluminum pipe rising 6" above ground. Set 6 ft. steel fence post R35E R35 1/2E 3.0 ft. north of corner. 1/4 S4 New BT's: RLS 1844 A 5" L. Pine bears N40°E, 29.6 ft., blazed and 1984

scribed: 1/4 S4 BT.

A 5" P. Pine bears S85°E, 33.3 ft., blazed and scribed: 1/4 S4 BT.

Brass LS 1844 disc in lower end of blazes. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys,

Compass Declination: 19 3/4°E Witness: Duane Scott

Corner is found 60 ft. west of Road 5160-040 and 110 ft. east of fence.

I hereby certify the above described corner monument and/or accessories was established as described on September 7, 1984.

REGISTERED PROFESSIONAL AND SURVEYOR OREGON DAVID E. SCOTT

File No. 1014

Office of County of	1844
State of	Hice UNION COUNTY SURVEYOR
OFFICIAL)	
Form R6-7100-57 (9/71)	Date Received 10-17-84 Date Filed GPO-798-278
	Date File GPO 798-276
	BY G. LANGLITZ DEPUTY