


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. C-13

History of original corner establishment:

The original subdivision of T6S, R35 1/2E was by W. Barr under Contract No. 492, approved Aug. 1, 1884. At this corner he set a stone 24x20x14, from which a 36" Pine bears East, 40 lks. and a 10" Pine bears N80°W, 42 lks.



Description of corner evidence found:

No corner monument found.

Bearing trees found:

- A 27" P. Pine with healed blaze bears S86°E, 27.5 ft.
- A 20" P. Pine with healed blaze bears N76°W, 28.7 ft.

Description of monument and accessories established to perpetuate the original location of this corner:

Set 2.5" aluminum cap on 2 3/8"x30" aluminum pipe rising 14" above ground in mound of dirt and stone. Set steel fence post 3.0 ft. north of corner.

Cap is stamped:

T6S R35 1/2E
1/4
S4+S3
RLS 1844
1984

Brass LS 1844 disc in lower end of blazes. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

A point at record bearing & distance from each of the original BT's left a 4 ft. gap for the corner location. Cap was set at center of 4 ft. gap.

Compass Declination: 19 3/4°E Witness: Duane Scott

Corner is found in the southeast quadrant of Rds 5160 & 5160-020, approx. 50 ft. off roads.

I hereby certify the above described corner monument and/or accessories was established as described on August 9, 1984.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David E. Scott

OREGON
JULY 13, 1979
DAVID E. SCOTT
1844

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received 10-17-84
Date Filed 10-24-84
 ☆ GPO-798-276

By G. LANGLITZ, DEPUTY
File No. 1016-84 R