CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. C-21

History of original corner establishment:
A post 3'x3"x3", 24" in ground. from which:

a 36" W. Larch bears N65°E, 34 lks. a 36" W. Larch bears S30°W, 12 lks.

Original corner established in 1883 by William B. Barr under contract #492

DIAGRAM T6S R35½E

T6S R35½I \$2|S1 RLS 1848 1986

Description of corner evidence found: None

Description of monument and accessories I established to perpetuate the original location of this corner:

Cap is stamped:

Set 2½"x30" aluminum capped aluminum pipe rising 6" no stones available. Set steel fencepost 3' north of corner.

New BT's

An 18" W. Larch bears N55%°W, 68.6 ft. blazed&scribed % S2BT
A 9%" Doug. Fir bears N62%°E 102.4 Ft., blazed&scribed % S1 BT

T6S R35½E

\$2|S1

RLS 1848

1986

Painted blazes and attached signs as required in <u>Specifications</u> <u>for Cadastral Surveys</u>, USFS Region 6, March, 1982.

Compass Declination: 19½°E
Witness: J. Sutton
I hereby certify that the above described corner monument and/or accessories was perpetuated as hereon described on Aug 21, 1986.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 13, 1979
B. A. SUTTON
1 8 4 8

SURVEYOR
Date Received 8-26-86
Date Filed 9-11-86
BY G. LANGLIZ DEPUTY

File No. 147-86 K

UNION COUNTY

Office of SEE SURVEY 27-86

(COUNTY OFFICIAL) (DEPUTY)