CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. G-21

History of original corner establishment:

Original corner established in 1883 by William B. Barr under contract #492.

Set Pine Post 3"x3"x3', 24" in ground. From which:
A 12" fir bears East, 30 lks.
A 12" fir bears S45°W, 18 lks.

T6S R35½E ¼ S11|S12

Description of corner evidence found:

No corner monument found.

BT's found:

A root crown that matches a 14" dead&down Fir with \square S visible bears S45°W, 18 lks. (Logging activity in the area appears to have moved this BT to the NW 10 ft.)

The root crown for a badly decayed fir with an open blazed slab bears East 30 lks., part of S&B visible.

Description of monument and accessories I established to perpetuate the original location of this corner:

Cap is stamped: T6S R35½E
From evidence, I set a ½"x30" aluminum
capped aluminum pipe rising 5" in a mound of stones.
Set steel fencepost 3 ft. North of corner.
RLS1848
1987

New BT's:

A 14" P. Pine bears N8°W, 7.3 ft., blazed&scribed: \$S11BT A 10" W. Larch bears S67°E, 58.9 ft., blazed&scribed: \$S12BT

Painted blazes and attached signs as per <u>Standard Specifications</u> for <u>Cadastral Surveys</u>, <u>USFS</u> Region 6, March 1982. A ½" brass disk stamped "RLS 1848" was nailed to the lower end of the blazes.

From USFS Rd. 5178, follow Rd. 5178017 0.2 miles North to the East-West fence line. Follow fence West ½ mile to fence corner. Corner is SW, approx. 80 ft.

Compass declination: 18½°E Witness: Jeremy Sutton

I hereby certify that the above described corner monument and/or accessories were established as hereon described on May 22, 1987.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 13, 1979
B. A. SUTTON
1 8 4 8

UNION COUNTY SURVEYOR

Date Received 8-19-87

Date Filed 8-Z4-87

By G. LANGLITZ DODITY

File No. 70-87 R

Office of	County of
State of I hereby certi	fy that the within instrument was filed in this office
for record on the day of	, 19
	by
(COUNTY OFFICIAL)	(DEPUTY)