


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. J-19

History of original corner establishment: Original corner established in 1884 by William B. Barr:

- A 4"x4"x30" Pine post was set, from which:
- A 12" Pine bears S40°E, 25 lks.
- A 36" Tamarack bears N15°W, 30 lks.



Description of corner evidence found:

No corner monument found.

Bearing trees found:

- 18" Western Larch, dead & down. Root hole bears N15°W, 30 lks. Open blaze scribed: 1/4 S BT.
- 18" green Ponderosa Pine bears S70°E, 25 lks. Open blaze scribed: 1/4 S BT. Blaze healed.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2.5"x30" aluminum capped aluminum pipe stamped:
Set steel fence post 3 ft. north of corner.

T6S R35 1/2E

New BT's:

6.5" Douglas Fir bears N28 3/4°W, 105.3 ft.,
blazed and scribed: 1/4 S11 BT

1/4 $\frac{S \cdot 11}{S \cdot 14}$

RLS 1848
1986

Attached 3/4" brass washer marked RLS 1848 to the lower blaze.

I hereby certify the above corner point was perpetuated as hereon described on February 21, 1986. USFS bearing tree signs were placed on all BT's and a 6" red band was painted around each BT.

Witness: M. Sutton

**UNION COUNTY
SURVEYOR**

Date Received 3-10-86

Date Filed 3-10-86

By G. LANGLITZ, Deputy

File No. 6-86 R

REGISTERED
PROFESSIONAL
LAND SURVEYOR

B. A. Sutton

OREGON
JULY 13, 1979
B. A. SUTTON
1848

Office of..... County of.....
 State of....., I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....
 by
 (COUNTY OFFICIAL) (DEPUTY)