


Index File No. V-17  
 T 6 S R. 35 1/2 E  
 Merid. Will.

**CORNER RECORD (SEARCH)**

Tract or Survey No. \_\_\_\_\_ Cor. No. \_\_\_\_\_

R.D. La Grande County Union  
 N.F. Willow-Whitman State Oregon

**CORNER DIAGRAM**



**DESCRIBE CORNER MONUMENT FOUND**

None

**DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND**

Sec 27 17" WL living, good condition seeds grown over  
Sec 26 Rotten D.F. stump w/ seeds visible  
Sec 35 dead + down 10" D.F. seeds visible + good condition  
Sec 34 dead + down 10" D.F. seeds visible + good condition

**PHOTO IDENTIFICATION DATA**

Photo No. \_\_\_\_\_  
 Filed At. \_\_\_\_\_  
 Object Ident. \_\_\_\_\_  
 Ident. By \_\_\_\_\_  
*Signature*

**DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER**

**PLANE COORDINATE POSITION DATA**

State \_\_\_\_\_ Zone \_\_\_\_\_  
 X \_\_\_\_\_  
 Y \_\_\_\_\_  
 Estab. By \_\_\_\_\_  
*Agency*

Signature <u>D. Dahlstrom</u>	Title <u>Forestry Aid</u>	Division _____	Headquarters _____	Date <u>10-8-69</u>	7100-52 REV. 65 5
----------------------------------	------------------------------	-------------------	-----------------------	------------------------	----------------------

**UNION COUNTY SURVEYOR**

---

Date Received \_\_\_\_\_

Date Filed 12-23-87

By G. LANGUITZ, DEPUTY

File No. 374-87R

V-17