


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. A-25

History of original corner establishment:

The Auxiliary Meridian between R35E and R35 1/2E was originally surveyed by Eugene P. McCormack under Contract No. 398, approved January 9, 1888. At this corner he set a post, pits, and a mound of earth and stones.



Description of corner evidence found:

No corner monument or other evidence found.

<b>UNION COUNTY SURVEYOR</b>
Date Received <u>10-17-84</u>
Date Filed <u>10-24-84</u>
By <u>G. LANGLITZ DEPUTY</u>
File No. <u>1001-84R</u>

Description of monument and accessories established to perpetuate the original location of this corner: Corner set by proportion.

Set 2.5" Aluminum cap on 2 3/8"x30" aluminum pipe rising 6" above ground. Cap is stamped:

Set steel fence post 3.0 ft. south of corner.

New BT's:

An 8" L. Pine bears S43.5°W, 109.0 ft., blazed and scribed: CC T6S R35E S1 BT.

A 5" L. Pine bears S10°E, 87.7 ft., blazed and scribed: X BT.

Brass LS 1844 disc in lower end of blaze. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

T5S R35E
S 33
S1   S4
R35E   R35 1/2E
T6S
CC
RLS 1844
1984

Compass Declination: 19 3/4°E

Witness: Duane Scott.

Corner is found 125 ft. west of the road through Vey Ranch, 2.1 mi. from Road 51.

I hereby certify the above described corner monument and/or accessories was established as described on September 6, 1984.

REGISTERED PROFESSIONAL LAND SURVEYOR
<i>David E. Scott</i>
OREGON JULY 13, 1970 DAVID E. SCOTT 1844

Office of..... County of.....  
 State of..... I hereby certify that the within instrument was filed in this office  
 for record on the..... day of....., 19.....  
 ..... by .....  
 (COUNTY OFFICIAL) (DEPUTY)