


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. C-22

History of original corner establishment:

None



Description of corner evidence found:

No corner monument or other evidence found.

**UNION COUNTY SURVEYOR**

---

Date Received 10-17-84

Date Filed 10-24-84

By G. LANGLITZ, DEPUTY

File No. 1004-84 R

Description of monument and accessories established to perpetuate the original location of this corner:

Set 2.5" aluminum cap on 2 3/8" aluminum pipe rising 4" above ground. Cap is stamped:

Set steel fence post 3.0 ft. south of corner.

New BT's:

A 17" L. Pine bears S70.5°E, 226.0 ft., blazed and scribed: CW 1/16 S1 BT.

A 4" L. Pine bears N77.5°W, 13.9 ft., blazed and scribed: ~~W~~BT, 16 S1 BT.

T6S R35E

C  $\frac{W}{S1}$   $\frac{1}{16}$  C

RLS 1844  
1984

Brass LS 1844 disc in lower end of blazes. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Compass Declination: 19 3/4°E

Witness: Duane Scott

Corner is found on west bank of Sheep Creek. Take Rd 5160-092 1/2 mi. north of fence. Corner is 250 ft. east of road.

I hereby certify the above described corner monument and/or accessories was established as described on September 5, 1984.

REGISTERED PROFESSIONAL LAND SURVEYOR

*David E. Scott*

OREGON  
JULY 13, 1979  
DAVID E. SCOTT  
1844

Office of..... County of.....

State of..... I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by .....  
(COUNTY OFFICIAL) (DEPUTY)