


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. E-19

History of original corner establishment:

The original subdivision of T6S, R35E, was by Herman D. Gradon under Contract No. 499, approved November 24, 2884. At this corner he set a stone 10x10x8, from which a 30" Pine bears N55°E, 33 lks. and a 24" Pine bears S60°E, 6 lks.



Description of corner evidence found:

Found stone 16x6x4 broken in half in small mound.

Bearing trees found:

- A 44" P. Pine bears N55°E, 23.3 ft. to center of healed blaze.
- A 42" P. Pine bears S64°E, 42.9 ft. to center of healed blaze.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2.5" aluminum cap on 2 3/8"x30" aluminum pipe rising 7" above ground. Buried stone on north side of pipe. Set steel fence post 3.0 ft. north of corner.

Cap is stamped:

T6S R35E
 1/4 $\frac{S2}{S11}$
 RLS 1844
 1984

Brass LS 1844 disc in lower end of blazes.
 Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Compass Declination: 19 3/4°E

Witness: Duane Scott

Corner is found on southeast slope of ridge. N64°W, 2100 ft., more or less, from the intersection of 5160 & 5160-140. Go 1800 ft. on Rd. 5160-140. Corner is 360 ft. west uphill.

I hereby certify the above described corner monument and/or accessories was established as described on August 2, 1984

UNION COUNTY SURVEYOR
Date Received <u>10-17-84</u>
Date Filed <u>10-24-84</u>
By <u>G. LANGLITZ, DEPUTY</u>
File No. <u>1009-84 R</u>

REGISTERED PROFESSIONAL LAND SURVEYOR
<i>David E. Scott</i>
OREGON JULY 13, 1979 DAVID E. SCOTT 1844

Office of..... County of.....
 State of....., I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....

(COUNTY OFFICIAL)

(DEPUTY)