


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. E-22

History of original corner establishment:

None



Description of corner evidence found:

No corner monument or other official accessories found.

There was a steel fence post with BLM tag marked "Approx 1/16" 0.2 ft. west of true location.

UNION COUNTY SURVEYOR
Date Received <u>10-17-84</u>
Date Filed <u>10-24-84</u>
By <u>G. LANGLITZ DEPUTY</u>
File No. <u>1011-84R</u>

Description of monument and accessories established to perpetuate the original location of this corner: Cap is stamped:

T6S R35E

Set 2.5" aluminum cap on 2 3/8"x30" aluminum pipe rising 6" above ground. Set steel fence post 3.0 ft. east of corner.

W 1/16 + $\frac{S1}{S12}$

RLS 1844
1984

New BT's:

A 13" L Pine bears N35 1/4°E, 195.7 ft., blazed and scribed: W 1/16 S1 BT.

A 6" L. Pine bears S47.1/4°E, 62.4 ft., blazed and scribed: W 1/16 S12 BT.

Brass LS 1844 disc in lower end of blazes. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Compass Declination: 19 3/4°E

Witness: Duane Scott

Corner is found on the east side of a meadow along Sheep Creek 500 ft. east of Road and 6 ft. north of east-west fence.

I hereby certify the above described corner monument and/or accessories was established as described on September 4, 1984.

REGISTERED PROFESSIONAL LAND SURVEYOR
<i>David E. Scott</i>
OREGON JULY 13, 1979 DAVID E. SCOTT 1844

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)