


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. E-23

History of original corner establishment:

The original subdivision of T6S, R35E was by Herman D. Gradon under Contract No. 499, approved November 24, 1884. At this corner he set a post, from which a 13" Black Pine bears N65°E, 9 lks. and a 10" Black Pine bears S16°W, 14 lks.



Description of corner evidence found:

No corner monument or other official accessories found.

Found a 6 ft. steel fence post with BLM tag marked "Approx. 1/4" 0.2 ft. north and 0.4 ft. west of corner.

Description of monument and accessories established to perpetuate the original location of this corner:

Cap is stamped:

At proportioned location, set 2.5" aluminum cap on 2 3/8" aluminum pipe rising 5" above ground. Set steel fence post 3.0 ft. west of corner.

T6S R35E
1/4 $\frac{S1}{S12}$
RLS 1844
1984

New BT's:

A 6" Tamarack bears N50 3/4°W, 87.7 ft., blazed and scribed: 1/4 S12 BT.

An 8" Tamarack bears S 22.5°W, 57.8 ft., blazed and scribed: 1/4 S12 BT.

Brass LS 1844 disc in lower end of blazes. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Compass Declination: 19 3/4°E

Witness: Duane Scott

Corner is found 11 fts south of the fence and 240 ft. east of Road 5160-060 at fence.

I hereby certify the above described corner monument and/or accessories was established as described on September 4, 1984.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David E. Scott

OREGON
JULY 13, 1979
DAVID E. SCOTT
1844

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR
Date Received <u>10-17-84</u>
Date Filed <u>10-24-84</u> <small>*GPO-798-276</small>
By <u>G. LANGLITZ, DEPUTY</u>
File No. <u>1012-84 R</u>