History of original corner establishment:

Original survey by General Land Office Contract survey 1884

The original notes state; Set a post for cor. to section 1 and 12 T6S R35EWM. From which.

A pine 5" in diam bears S65°W 18 lks dist marked T6S R35E S12BT; A pine 4" in diam bears N35°W 34 lks dist marked T6S R35E S1BT;

	E-25
DIAGRAM	
R35EWM S1 S12	R35½EWM S4

Description of corner evidence found:

Found a stump with log on the ground with scribe visible at N35°W 34 lks dist.

UNION COUNTY SURVEYOR	
Date Received	REGISTERED OREGON LAND STRVEYOR
Date Filed	James & Cole
By	DAMES G. VOELZ B81

Description of monument and accessories I established to perpetuate the original location of this corner

Set a 2" galvanized pipe 30" long with bronze cap on top and 8" plate welded to bottom. The pipe set to a depth of 22" and back filled with stone and tamped soil,

I stamped the disk.

SCOR T6S R35E R35½E S12 S4 S12 ORE LC 381 1969

I established three new bearing trees. From the monument

the new bearing trees are; A pine 30" in diam bears N18°E 49.6 ft.

dist marked T6S R35½E S4BT; A tamarack 18" in diam bears S48°W 35.4

ft. dist marked T6S R35E S12BT; A black pine 8" in diam bears N50°W 10.4 ft.

dist marked T6S R35E S1BT; Distance measured to center of respective trees

and marked with a scribe. I set a steel fence post with USFS sign 54-4 attached.

USFS national forest boundary signs were placed on the post indicating National

Forest land to South and East. USFS bearing tree signs were placed on the bearing trees shoulder high facing the corner.

Office of	County of Union
State of Oragon , I hereby certify th	at the within instrument was filed in this office
for record on the 20. day of Sept. Co surveyor	(DEPUTY)
(COUNTY OFFICIAL)	(DEPUTY)

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

The original subdivision of T6S, R35E was by Herman D. Gradon under Contract No. 499, approved November 24, 1884. At this corner he set a post, from which a 5" Pine bears S65°W, 18 lks. and a 4" Pine bears S65°W, 18 lks.

DIAGRA	M	
T	6S	
R35E	R35	1/2E
. 1		
12		

Poscription of corner evidence found:

Found brass 3" Cap on 2" I.D. iron pipe rising 8" above ground. This cap represents a monumentation of the original location, and bears \$88°10'57"W, 17.11 ft. from intersection point.

Found one bearing tree, a 27" P. Pine bearing N18°E, 49.6 ft., healed blaze. Tree is dead.

S COR T6S R35 1/2E R35E S1 S12 ORE LIC 381 1969

*Stamped AM on monument by LS 381.

Corner by LS 381 is recorded on document #729-84R with the Union County Surveyor.

Description of monument and accessories | established to perpetuate the Cap is stamped:

original location of this corner:

Set 2.5" aluminum cap on 2 3/8" aluminum pipe at R35E T6S

true intersection location rising 6" above ground.

Distance from old brass cap to new aluminum cap
is 17.11 ft. Stamped AM on old B.C. by LS 381.

Aluminum cap is set at intersection on Standard Range Line.

New BT's:

RLS 1844

A 7" Fir bears S83°W, 22.7 ft., blazed and scribed: T6S R35E S12BT.

A 6" Fir bears N 25.5°W, 24.9 ft., blazed and scribed: T6S R35E S1 BT.

The 27" P. Pine by LS 381 bears N1°E, 46.1 ft. from true corner.

Brass LS 1844 disc in lower end of blazes. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Compass Declination: 19 3/4°E Witness: Duane Scott

Corner is found 46 ft. southeast of fence corner and 500 ft. north of intersection of Rds. 5160-050 and 5160-056.

I hereby certify the above described corner monument and/or accessories was established as described on September 19, 1984.

REGISTERED PROFESSIONAL LAND SURVEYOR

wid E. Scot

OREGON
JULY 13, 1979
DAVID E. SCOTT
1844

Office of	County of		_
State of, / hereby certification	fy that the within instrument was fi	iled in this officeUNION COUNTY	,
for record on the day of		SURVEYOR	
	by		
(COUNTY OFFICIAL)	(DEPUTY)		A

Form R6-7100-57 (9/71)

Date Received 10-17-84

10-24-84

Date Filed GPO 798-276

By G. LANGLITZ DEPUT