


USDA-FOREST SERVICE

Index File No. Z-21
T 6S R. 35E
Merid. WILL.

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or Survey No. _____
Cor. No. _____
R.D. DALE County UNION
N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

CHAINING WEST, 107.6 FT FROM 2/1 I FIND A ROOT HOLE WHICH FITS LOCATION OF THE CORNER TREE.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

ROOT HOLES FIT THE LOCATION OF BOTH ORIGINAL B.T.'S THERE IS SMALL FRAGMENTS OF CHARRED WOOD AROUND THESE 3 ROOT HOLES, BUT NONE HAVE SCRIBES OR BLAZES ON THEM.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

NO SIGNS WERE PUT UP.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At _____
Object Ident. _____
Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature Dennis L. Hayford *Title* _____ *Division* PLS 1636 *Headquarters* _____ *Date* 9-14-82 7100-52 (3.68)

UNION COUNTY SURVEYOR
Date Received _____
Date Filed 12-23-87
By G. LANGUITZ, DEPUTY
File No. 371-87R

2-21