CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. A-03

History of original corner establishment:

None.

DIAGRAM

T5SR36E ½ S6 T6SR36E

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

Cap is stamped:

Corner set by single proportioning. I set a 2½"x30"

Aluminum capped aluminum pipe rising 6" in a mound of stones. Set steel fencepost 3' North of corner.

T5SR36E

15SR36E

RLS1848

New BT's:

A 6" D. Fir bears S7¾°E, 17.5 ft., blazed&scribed: ¼S6BT
An 8½" D. Fir bears S70½°E, 17.5 ft., blazed&scribed: ¼S6BT

Painted blazes and attached signs as per <u>Standard specifications</u> for <u>Cadastral Surveys</u>, <u>USFS</u> Region 6, March 1982. A ³/₄" brass disk stamped "RLS 1848" was nailed to the lower end of the blazes.

From the standard % cor. on the South line of sec. 31 on top of a North-South ridge, go East, 700 ft. corner is on Northerly slope, 350 ft. East of a private road, 120 ft. North of a ridge sloping to the East-Northeast.

Compass declination: 18⅓E Witness: Jeremy Sutton

I hereby certify that the above described corner monument and/or accessories were established as hereon described on June 30, 1987.

PROFESSIONAL LAND SURVEYOR

OREGON
JULY 13, 1979
B. A. SUTTON
1 8 4 8

UNION COUNTY SURVEYOR

Date Received 8-19-87

Date Filed 8-24-87

By G. LANGLITE DORTY

File No. 77-87 R

0//:	
Office of	ounty of
Ctota of	ounty br
State of, I hereby certify that	the within instrument was file to the
for record on the	the within instrument was filed in this office
for record on the day of	, 19
(COUNTY OFFICIAL)	
COUNTY OFFICIAL	
	DEPLITY