


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. A-04

History of original corner establishment:

None.



Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

Corner set by single proportioning. I set a 2½"x30" aluminum capped aluminum pipe rising 10" in a mound of stones. Set steel fencepost 3' South of corner.	Cap is stamped: T5S R36E
--	--------------------------

New BT's:

A 4½" W. Larch bears S1¼°W, 16.2 ft., blazed&scribed:	E1/16S6BT
A 5½" W. Larch bears S53½°E, 22.1 ft., blazed&scribed:	E1/16S6BT

Painted blazes and attached signs as per Standard specifications for Cadastral Surveys, USFS Region 6, March 1982. A ¾" brass disk stamped "RLS 1848" was nailed to the lower end of the blazes.

From the posted line on Rd. 5178095 200 ft. West of the closing corner between S6|S5 go North 600 ft., un-numbered road goes West up a draw. Follow for 600 feet to fork, take left fork Southwesterly 800 feet to posted line, corner is West up the hill 200 feet on Easterly slope.

Compass declination: 18°E
Witness: Jeremy Sutton

I hereby certify that the above described corner monument and/or accessories were established as hereon described on July 2, 1987.

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Jeremy Sutton
**OREGON
JULY 13, 1978
J. A. SUTTON
1848**

UNION COUNTY SURVEYOR
Date Received <u>8-19-87</u>
Date Filed <u>8-24-87</u>
By <u>G. LANGLITZ, DEPUTY</u>
File No. <u>78-87 R</u>

Office of..... County of.....
 State of....., I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....
 by

(COUNTY OFFICIAL)

(DEPUTY)