CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. A-05

History of original corner establishment:

Original corner established in 1883 by William B. Barr under contract #492. He set a basalt stone 20"x12"x12" and dug pits S, E, & W. of corner.

DIAGRAM

T5SR36E S32 S6 S5 T6S R36E CC

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

Cap is stamped: Corner set by single proportioning. I set a 2⅓"x30" aluminum capped aluminum pipe rising 7". Few stones available. Set steel fencepost 3' East of corner.

T5SR36E S32 S6 S5 T6S R36E CC RLS1848

1987

New BT's:

A 7" W. Larch bears S803°W, 11.4 ft.,

blazed&scribed: T6SR36ES6CCBT A 7" D. Fir bears S32°E, 51.3 ft., blazed&scribed: T6SR36ES5CCBT

Painted blazes and attached signs as per Standard specifications for Cadastral Surveys, USFS Region 6, March 1982. A 3 brass disk stamped "RLS 1848" was nailed to the lower end of the blazes.

From Rd. 5125, take Rd. 5178095 approx. 1 mile. Corner is across the draw to the East, 250 ft.

Compass declination: 184°E Witness: Jeremy Sutton

I hereby certify that the above described corner monument and/or accessories were established as hereon described on May 11, 1987.

REGISTERED **PROFESSIONAL** LAND SURVEYOR

> OREGON JULY 13, 1979 B. A. SUTTON

UNION COUNTY SURVEYOR

Date Received 8-19-87

Date Filed 8-24-87

79-87 Fle No.

Office of	County of
	that the within instrument was filed in this office
for record on the day of	
b	y
(COUNTY OFFICIAL)	(DEPUTY)