## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. C-04

History of original corner establishment:

None.

DIAGRAM

T6SR36E CE 1/16 56

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the

original location of this corner:

Cap is stamped:

T6S R36E E1/16 S6 C RLS1848

1987

Corner set by single proportioning. I set a 2½"x30" aluminum capped aluminum pipe rising 10" in a mound of stones. Set steel fencepost 3' South of corner.

New BT's:

CE1/16S6BT A 9½" D. Fir bears N17½°W, 43.2 ft., blazed&scribed: An 11" D. Fir bears S88°W, 56.1 ft., blazed&scribed: CE1/16S6BT

Painted blazes and attached signs as per Standard specifications for Cadastral Surveys, USFS Region 6, March 1982. A 3 brass disk stamped "RLS 1848" was nailed to the lower end of the blazes.

From Rd. 5178095, take Rd. 5178123 approx. 200 ft. Corner is up hill to the East, 120 ft.

Compass declination: 184°E Witness: Jeremy Sutton

I hereby certify that the above described corner monument and/or accessories were established as hereon described on July 1, 1987

REGISTERED PROFESSIONAL LAND SURVEYOR

> OREGON JULY 13, 1979 B. A. SUTTON 1 8 4 8

UNION COUNTY SURVEYOR

Date Received 8-19-87

Office of...... County of..... State of......, I hereby certify that the within instrument was filed in this office for record on the...... day of...... , 19..... ..... by ..... (COUNTY OFFICIAL) (DEPUTY)