CERTIFIED RECORD OF LAND CORNER MONUMENTATION G-09

History of original corner establishment:

Original corner established in 1884 by William B. Barr under contract #492. Set a Pine post, 3½x3½x4', 24" in ground. From which:

A 10" Pine bears N30°E, 20 Lks. A 10" Pine bears S20°W, 6 Lks.

DIAGRAM T6S R36E 1 S8 \$ S9

Description of corner evidence found:

Found no trace of original post. Found the following original bearing trees: A 14" Lodgepole Pine bears N30°E, 20 Lks., open blaze; 'ASBT' visible. An 11" Lodgepole Pine, dead & down, bears S20°W, 6 Lks., 'SBT' visible in open blaze.

Description of monument and accessories I established to perpetuate the

original location of this corner: Cap is stamped: At the position established from the orig. bearing

T6S R36E Trees, I set a 25"x30" aluminum capped aluminum pipe rising 5". No stones available. Set steel fence post

S8 + S9 RLS1848 1987

3 ft. North.

New BT's: A 5" W. Larch bears N62%°E, 73.0 ft., blazed&scribed: \$59BT A 9" W. Larch bears N39%°W, 68.7 ft., blazed&scribed: \$58BT

Painted blazes and attached signs as per <u>Standard specifications</u> for <u>Cadastral Surveys</u>, <u>USFS</u> Region 6, March 1982. A 4" brass disk stamped "RLS 1848" was nailed to the lower end of the blazes.

Go to East end of 5178159. Skid road goes East and curves North from landing. Corner is 250 ft. ENE Skid road goes East and from landing at the top of easterly slope.

Compass declination: 21%°E Witness: Jeremy Sutton

I hereby certify that the above described corner monument and/or accessories were established as hereon described on June 26, 1987.

REGISTERED **PROFESSIONAL** LAND SURVEYOR

> OREGON JULY 13, 1979 B. A. SUTTON 1 8 4 8

UNION COUNTY SURVEYOR

Date Received 8-19-87

Date Filed 8-24-87

BY G. LANGLITZ DEPUTY

File No. 88 - 87 R

Office of	County of
State of / hereby certify t	hat the within instrument was filed in this office
for record on the day of	, 19
(COUNTY OFFICIAL)	(DEPUTY)