## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established in 1883 by William B. Barr under Contract No. 492.

A 15"x10"x10" stone was set, from which:

- a 12" Pine bears N25°E, 32 lks., a 10" Pine bears S55°E, 23 lks., a 12" Pine bears S15°W, 40 lks., and a 40" Tamarack bears N60°W, 25 lks.

Index File No. N-17

DIAGRAM

T6S R36E

15 14 22 23

## Description of corner evidence found:

No corner monument found.

Bearing trees found:

8" Pine, dead & down, bears N25°E, 32 lks., blaze & scribing visible: T6S R36E S14 BT.

Rotted remains of Pine dead & down, bears S15°W, 40 lks., no marks visible, portion of overgrowth visible.

27" W. Larch, dead standing, bears N60°W, 25 lks., opened blaze, visible: 6E.

Description of monument and accessories lestablished to perpetuate the Cap is stamped: original location of this corner:

Set 2.5"x30" aluminum capped aluminum pipe rising 6" in mound of stones. Set steel fence post 3 ft. north of corner.

S15 S14 S22 S23

T6S R36E

New BT's:

RLS 1848 1986

8" W. Larch bears N48 3/4°E, 38.7 ft., blazed & scribed: T6S R36E S14 BT.

12" D. Fir bears S40 1/2°E, 24.5 ft., blazed & scribed: T6S R36E S23 BT. 12.5" W. Larch bears S9 1/4°W, 52.0 ft., blazed & scribed: T6S R36E S22 BT.

15" W. Fir bears N84°W,23.1 ft., blazed & Scribed: T6S R36E S15 BT.

Painted blazes and attached signs as required in Specifications for Cadastral Surveys, USFS Region 6, March 1982. Attached 3/4" brass washer marked RLS 1848 to blazes.

Compass Declination: 19 1/2°E Witness: J. Sutton

I hereby certify that the above described corner monument and/or accessories was perpetuated as hereon described on May 26, 1986.

REGISTERED PROFESSIONAL LAND SURVEYOR

> OREGON JULY 13, 1979 B. A. SUTTON 1 8 4 8

Office of	County of
(COUNTY OFFICIAL)	(DEPUTY)
26-7100-57 (9/71)	Date Received 5-27-86

Form R6-7100-57 (9/71)

☆U.S. GOVERNMENT PRINTING OFFICE - 1983 - 793 - 276

Date Filed 5-27-86 By G. LANGLITZ DEPUTY

File No. 53-86 R