


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. B-1

History of original corner establishment:

Not set.



Description of corner evidence found:

None.

Description of monument and accessories established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" x 30" galvanized pipe and brass cap marked:  
Set pipe 25" in the ground and small mound of stone around to cap.  
From which, by magnetic declination of N20°E:  
A 10" tamarac bears N86°E, 33.1 ft. scribed N 1/16 S6 BT. A 12" tamarac bears N35°W, 24.5 ft. scribed T6SR37E BT. Placed 54-3s and brass washers stamped PLS 1051 on BTs. Painted blazes red and 6" red band around. Placed 54-2 and 54-4 on steel fence post 5' East and 54-2 and 54-9 on steel fence post 5' North of corner.

T6S R38E  
N 1/16  
R37E — S6  
OR PLS 1051  
1979

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Robert S. Stevens  
Jerry Rous

September 20, 1979

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Barry B. Barbour*

OREGON  
OCT. 17, 1975  
BARRY B. BARBOUR  
1051

Office of..... County Surveyor..... County of..... Union.....  
State of..... Oregon..... I hereby certify that the within instrument was filed in this office  
for record on the 6th day of December..... 1979

*J. V. [Signature]* (COUNTY OFFICIAL) by *[Signature]* (DEPUTY)

**UNION COUNTY SURVEYOR**

Date Received \_\_\_\_\_

Date Filed \_\_\_\_\_

By \_\_\_\_\_

File No. ~~748-84R~~ 748-84R