
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. B-3

History of original corner establishment:

Not set.



T6SR38E

Date Filed

File No. 749-84 R

Description of corner evidence found:

None.

Corner is 75' north of track road on East side of old fence.

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" x 30" galvanized pipe and brass cap marked:

Set pipe 16" in the ground to bedrock and mound of stone around to cap.

From which, by magnetic declination of N20°E:

OR PLS 1051

A 6" pine bears N26°E, 37.9 ft. scribed CN 1979

1/16 S6 BT. A 12" pine bears S70°W, 42.7 ft. scribed

CN 1/16 S6 BT. Placed 54-3s and brass washers stamped PLS

1051 on BTs. Painted blazes red and 6" red band around.

Placed 54-2 and 54-4 on steel fence post 5' South , and

54-2 and 54-9 on steel fence post 5' West of corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
OCT. 17. 1975
BARRY B. BARBOUR
1 0 5 1

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Robert S. Stevens Cheryl Remmerde

September 14, 1979

Office of County Surveyor County of Union State of Oregon . I hereby certify that the within instrument was filed in this county of	
for record on the 6.th. day of December	UNION COUNTY SURVEYOR
Form R6-7100-57 (9/71)	Date Receixed

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:


Corner set by Barry B. Barbour, LS 1051, as described by File No. 749-84R, filed December 6, 1979, in the records of the Union County Surveyor.

Record states: Corner is 75' north of track road on East side of old fence.

At surveyed point set 2½" x 30" galvanized pipe and brass cap marked (as shown below): Set pipe 16" in the ground to bedrock and mound of stone around to cap.

From which, by magnetic declination of N20°E:

A 6" pine bears N26°E, 37.9 ft. scribed CN1/16 S6 BT. A 12" pine bears S70°W, 42.7 ft. scribed CN1/16 S67 BT.




Description of corner evidence found:

Found 2% ins. diam. iron pipe, projecting 12 ins. above ground, with 3 ft diam mound of stone to top, pipe on West side center of 4 ft. x 4 ft. rock jack, with 2% ins. diam. brass cap, marked as shown: From the recovered monument I find the Barbour bearing trees:

An 8 ft. high cut pine stump, bears N. 26° E., 37.9 ft. dist. to face.

A ponderosa pine, 19 ins. diam., bears S. 70° W., 42.7 ft. dist. to face, alive and healthy, with healed double blaze.



Description of monument and accessories I established to perpetuate original location of this corner:

New bearing tree:

A ponderosa pine, 12 ins. diam., bears N. 42° E., 49.2 ft. dist., mkd. CN1/16 S6 BT.

Set guard posts ±5 ft W'ly with Property Boundary (54-2) sign and ±5 ft S'ly with Property Boundary (54-2) and Land Survey Monument (54-9) signs attached.

New bearing tree marked on a single blaze and has a nail with a brass washer stamped "LS 2648" right side center for distance measurements.

Painted 6 ins. red bands and added Bearing Tree (54-3) and Land Survey Monument (54-9) signs as needed to all bearing trees.

Auto C/A geographic position: Lat. 45°04'28.5" N

Long. 118°06'20.5" W

I hereby certify that the corner is monumented and accessories taken as described, using a Warren Knight staff compass, set with 15° East declination, and steel tape on September 20, 2014.

Witnesses: Brenda Johnson and Justin Seal

REGISTERED PROFESSIONAL LAND SURVEYOR

Deceased

OREGON JANUARY 18, 1994 RON C. WALTER 2648

Renewal Date: June 30, 2016

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
July 22, 1977
WILLIAM R. WELLS
1106

Renewal Date: June 30, 2016

	ı
UNION COUNTY	
SURVEYOR	
Date Received 2 25 15	
Date Filed 2 25/15	
By Al GAli	e se i
File No. <u>056-70151</u>	

NOTE: See "Explanation for Successor Certifying Surveyor" statement in Narrative of Record of Survey , CS 010-2015, filed concurrently with this Land Corner Record.