


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. C-4

History of original corner establishment:

None.



Description of corner evidence found:

Not Set.


Corner is on East slope about 250' East of the road.

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 1" X 36" galvanized pipe and brass cap marked: Set pipe 30" in the ground and small mound of stone around to cap.

From which by magnetic declination of N20°E: A 10" Pine bears S61°W, 18.0 ft. scribed CE1/16S6 BT. A 12" Tamarac bears N37°W, scribed CE1/16S6 BT. Placed CZ location tags, CZ Do Not Cut tags, and CZ property corner tags. Placed 54-4 on steel fence post 5' South of the corner.

T6S R38E  
E1/16



OR PLS 1051  
1980

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Daniel T. Rowland  
Robert Boling

June 5, 1980

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Barry B. Barbour*

OREGON  
OCT. 17, 1975  
BARRY B. BARBOUR  
1051

Office of..... County Surveyor..... County of..... Union.....

State of..... Oregon....., I hereby certify that the within instrument was filed in this office for record on the 3rd day of July, 1980

..... by ..... (COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY SURVEYOR**

Date Received \_\_\_\_\_  
★ GPO-756-276

Date Filed \_\_\_\_\_

By \_\_\_\_\_

File No. 758-84R