CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. D-5

History of original corner establishment:

None.

DIAGRAM T6S R38E S1/16 S6 S5

T6S R38E

S5

S1/16

Description of corner evidence found:

Not Set.

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 1" X 36" galvanized pipe and brass cap marked: Set pipe 30" in the ground and mound of stone around

OR PLS 1051 1980 From which by magnetic declination of N20°E: An 8" Tamarac

bears N27°W, 45.7 ft. scribed S1/16S6 BT. A 12" Fir bears S80°E, 42.4 ft. scribed S1/16S5 BT. Placed CZ location tags, CZ BT Do Not Cut tags, CZ property corner tags and brass washers stamped PLS 1051. Placed 54-4 on steel fence post 5' West of the corner. Placed CZ location tag 50' South on road.

> REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON BARRY B. BARBOUR I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Daniel T. Rowland Robert Boling

June 5, 1980

	County S	mueron		Union		
Office of	County 5	ırveyor	County of	OHIOH		•••••
State of	regon	. , I hereby certif	y that the within	instrument we	as filed in this	office

(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

UB	MOIL	COMMIAN
•••••	20K	NEAO 3

Date Received

Date Filed