CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

W. Barr surveyed the westerly portion of T. 6 S. R. 38 E., W.M. under GLO contract No. 388 dated May 7 1881.

Record states:

Marked basalt rock 10 x 8 x 8 for ¼ sec corner raised mound of rock as per instructions.

E - 15DIAGRAM T 6 S R 38 E 1/4 PLS 1206 1991

J. W. Kimbrell, Union County Surveyor, subdivided sections 3,4,9, and 10 on December 7, 1889. His survey notes are on pages 224-227 of an old bound survey book on file in the Union County Surveyors Office. Kimbrell found the above described ¼ corner and most likely chiseled the "CS" which we found on the stone. Office.

Description of corner evidence found:

Found set stone 10" x 8" x 8" in scattered stone mound marked with "CS on face.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the point previously occupied by the found stone, set 1¼" x 30" galv. iron pipe 24" into the ground, constructed 36" dia. stone mound around the monument. 2½" dia. brass cap is marked as shown in the corner diagram.

From which, bearing objects:
A 5/8" dia. x 30" long rebar bears N. 45° E., 25.0 feet S. 45° E., 25.0 .. S. 45° 91 W., 25.0 .. N. 45° W., 25.0

All rebars have yellow plastic attached. Caps are marked "HANLEY ENGR. PLS 1206". Buried the original corner stone 1' north of the monument. Set fence post 2' west of the monument, attached USFS 54-9 sign to the fence post.

I certify that the above corner was properly monumented under my direct supervision on August 28, 1991, as witnessed by Larry McBroom and David Smith.

Office of ... County ... Surveyor County of Union State of Oregon , I hereby certify that the within instrument was filed in this office for regord on the . I. day of ... Sept UNBON COUNTY you To Blenter SURVEYOR (COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

REGISTERED PROFESSIONAL LAND SURVEYO

> one of Hon OREGON JAMES D. HANLEY 1206

☆ GPO-798-276