


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. F-1

History of original corner establishment:

Not set.




Description of corner evidence found:

None.

Corner falls on East slope in scattered small pine.

Description of monument and accessories established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" x 30" galvanized pipe and brass cap marked:
 Set pipe 8" in the ground to bedrock and mound of stone around to cap.
 From which, by magnetic declination of N20°E:
 A 20" pine bears N30°W, 47.5 ft. scribed N 1/16 S7 BT. A 12" fir bears S25°E, 68.1 ft. scribed T6SR37E BT. Placed 54-3s and brass washers stamped PLS 1051 on BTs. Painted blazes red and 6" red band around. Placed 54-2 and 54-4 on steel fence post 5' East and 54-2 and 54-9 on steel fence post 5' North of corner.



I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Robert S. Stevens
Jerry Rous

September 21, 1979

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Barry B. Barbour

OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051

Office of.....County Surveyor..... County of.....Union.....

State of.....Oregon..... I hereby certify that the within instrument was filed in this office

for record on the...6th day of...December....., 1979.

B. Barbour
(COUNTY OFFICIAL)

by *J. Rous*
(DEPUTY)

UNION COUNTY SURVEYOR	
Date Received	_____
Date Filed	_____
By	_____
File No.	<u>772-84R</u>