CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

J.W. Kimbrell, Union County Surveyor in 1889 subdivided sections 3,4,9 and 10 of Township 6 South, Range 38 East on December 7, 1889. His survey notes are contained on pages 224-227 in an old bound survey book on file in the Union County Surveyors office. He set this 1/16 corner during this survey. Kimbrells notes on page 224 states: Set post for 1/8 corner, from which:

F-13

DIAGRAM

T 6 S R 38 E

KIMBRELL N1/16

S 9 | S 10

PLS 1206

1991

A Pine 20 inch dia. bears N. 51° E. 26 lks. dist.

Description of corner evidence found:

Found 2' dia. stone mound, none of the stones are marked. From which:
A down and partially rotted Ponderosa Pine, size indeterminate,
bears N. 51° E., 17.2 feet dist. marked partial blaze and chop marks visible.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the center of the 2' dia. stone mound, set 1%" x 30" galv. iron pipe 20" into the ground, constructed 24" dia. stone mound around the monument. 2%" brass cap is marked as shown in the corner diagram.

From which, new bearing trees:
A 9" dia. Ponderosa Pine bears N. 81° E., 20.5 feet dist.

marked Kimbrell N1/16 S10 BT on double blaze.

A 9" dia. Ponderosa Pine bears N. 12° W., 7.3 feet dist. marked Kimbrell N1/16 S9 BT on double blaze.

Set fence post 2' south of monument. Attached U.S.F.S. 54-3 sign to bearing trees.

I certify that the above corner was properly monumented under my direct supervision on November 6, 1991, as witnessed by Larry McBroom and Mike Parker.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
SEPTEMBER 23, 1977
JAMES D. HANLEY
1206

		-
Office of County Surveyor	County of Union	
State of State of	certify that the within instrument was filed in the	nis office
for record on the day of		
(COUNTY OFFICIAL)	SURVEYOR (DEPUTY)	
Form R6-7100-57 (9/71)	Data Received 12/18/91	
	Data Filed 12/20/9/	

☆ GPO-798-276