


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. G-1

History of original corner establishment:

Corner was originally established by W. B. Barr, under G.L.O. contract No. 388, in September, 1881. Surveyors General's notes state: "Marked basalt rock 12 x 10 x 6 for 1/4 sec. corner from which Pine 24 in. diam. bears S52°W, 22 lks. dist. Pine 15 in. diam. bears S44°E, 76 lks. dist."



Description of corner evidence found:

Found no trace of corner stone. Found old rotten pine stump with 54-3 and visible scribing. Measured N52°E, 14.5 ft. from which another old pine stump bears S44°E, about 50 ft. Also 54-3 on it.


Description of monument and accessories established to perpetuate the original location of this corner:

At center of above described point set 2 1/2" x 30" galvanized pipe and brass cap marked: Set pipe 18" in the ground and small mound of stone around to cap.

From which, by magnetic declination of N20°E:

An 11" fir bears N71°E, 33.2 ft. scribed 1/4 S7 BT.

A 12" fir bears S84°W, 13.8 ft. scribed T6SR37E. Placed 54-3s and brass washers stamped PLS 1051 on BTs. Placed 2 54-5s on tree 5' East. Painted blazes red and 6" red band around. Placed 54-4 on steel fence post 5' South of corner.



OR PLS 1051
1979

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: David L. Landers
Robert S. Stevens

July 20, 1979

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Barry B. Barbour

OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051

Office of.....County Surveyor..... County of..... Union.....

State of..... Oregon....., I hereby certify that the within instrument was filed in this office
for record on the 6th day of December..... 1979

..... by
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR
Date Received _____ <small>* GPO-798-276</small>
Date Filed _____
By _____
File No. <u>777-84 R</u>