CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

W.B. Barr Performed most of the subdivision of Township 6 South Range 38 East W.M., under GLO contract No. 388. Dated May 7, 1881.

Record States:

Set Stake... from which

Pine 30 in. diam. bears N. 54 W. 115 lks. dist. Pine 15 in. diam. bears N. $42\frac{1}{2}$ E. 131 lks. dist.

G - 13

1990

DIAGRAM

T6S R38E 1 S9\$10 PLS 1206

Description of corner evidence found:

Stone (not of record) 8" x 8" x 8" set flush with the ground, marked with $\frac{1}{4}$ on west side.

A stump hole bears N. $42\frac{1}{2}$ E. 86.5 feet dist. A 30" rotted Pine stump, 36" high bears N. 54 W. 75.9 feet dist. marked BT.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the corner point previously occupied by the found stone, set 1_4^{1} ' x 30" galv. iron pipe 26" into ground, with 2_2^{1} " diam. brass cap marked as shown in the corner diagram. Buried original stone 1' North. No stone mound constructed.

From which, new bearing trees:

A 12" diam. Ponderosa Pine bears N. 84 W. 31.7 feet diam. marked

1 S9 BT on double blaze.

A 6" diam. White Fir bears N. 15 W. 66.3 feet dist. marked

1 S9 BT on double blaze.

An 8" diam. Douglas Fir bears N. 45 E. 51.1 feet dist. marked

4 S10 BT on double blaze.

A 9" diam. Ponderosa Pine bears S. 35 E. 21.1 fees dist. marked

4 S10 BT on doulbe blaze.

Attached USFS 54-9 and 54-3 signs to all bearing trees set fence post 2' north of monument with 54-9 sign attached.

I certify that the above corner was property monumented under my direct supervision on June 1, 1990 as witnessed by Tom Fisk, Larry McBroom and Andy Marlette. REGISTERED

> enul OREGON JAMES D. HANLEY

PROFESSIONAL LAND SURVEYOR

Office of ... County Surveyor County of ... Union State of Oregon / hereby certify that the within instrument was filed in this office

..... by (COUNTY OFFICIAL)

(DEPUTY)

Form R6-7100-57 (9/71)

Date Receive

UNION COUNTY

SURVEYOR