CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was originally established by W. H. Barr, under GLO contract No. 388. in September, 1881. Surveyors General's notes state: "Set stake 4 ft. long, 4 ins. diam. 18 ins. in ground for 1/4 Sec. Corn from which; Pine 8 ins. diam. brs. S45°E, 6 lks. dist. Pine 12 ins. diam. brs. N33 1/2°E, 13 lks. dist."

Hanely Engineering had information that placed the section corner for sections 7, 8, 17 and 18 to a new position. I agreed to this position and they monumented the corner in March, 1981. The new position moved this corner and it was reset April 8, 1981.

Index File No. J-3

DIAGRAM
T6SR38E
S7

1/4 — I
S18

Description of corner evidence found:

No trace of corner could be found during two searches. A steel fence post with BIM tag marking approximate corner location was found. Corner falls on edge of small thicket of fir, about 150' North and 125' East of main road.

Description of monument and accessories I established to perpetuate the original location of this corner:

At new surveyed point set 2 1/2" x 30" galvanized pipe and brass cap that was set in 1979. Cap Marked:
Set pipe 24" in the ground and mound of stone around to cap.
From which by magnetic declination of N20°E:
A 14" Fir bears N45°E, 43.4 ft. scribed 1/4 S7 BT.
A 16" Pine bears S47°W, 64.6 ft. scribed 1/4 S18 BT.
Placed 54-3s, 54-4s and brass washers stamped PLS 1051 on BTs.
Defaced Old BTs
Placed 54-4 on steel fence post 5' east.

RESET 1981 T6SR38E S7 1/4 — — — — S18 OR PLS 1051 1979

File No. 790-84 R

PROFESSIONAL LAND SURVEYOR

Barry B. Barbour OREGON OCT. 17, 1975 BARRY B. BARBOUR I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Daniel Rowland Douglas Moser

April 8, 1981

Office of County Surveyor. County of Union.	
State of Oregon I hereby certify that the within instrument was filed in for record on the 25 day of June 1981 Howard L Percy by John Charles (COUNTY OFFICIAL)	UNION COUNTY SURVEYOR
Form R6-7100-57 (9/71)	Date Received 274
	Date Filed

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. J-3

History of original corner establishment:

Corner was originally established by W. B. Barr, under GLO contract No. 388, in September, 1881. Surveyors General's notes state: "Set stake 4 ft. long, 4 ins. diam. 18 ins. in ground for 1/4 Sec. cor. from which

Pine 8 ins. diam. brs. S45°E, 6 lks. dist. Pine 12 ins. diam. brs. N33 1/2°E, 13 lks. dist."

DIAGRAM
T6SR38E
S7
1/4 ———
S18

Description of corner evidence found:

No trace of corner could be found during two searches. A steel fence post with BLM tag marking approximate corner location was found. Corner falls on edge of small thicket of fir, about 150' North and 125' East of main road.

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" x 30" galvanized pipe and brass cap marked:

Set pipe 24" in the ground and small mound of stone around to cap.

From which, by magnetic declination of N20°E:

A 6" fir bears N08°E, 17.1 ft. scribed 1/4 S7

BT. A 7" fir bears S43°W, 38.7 ft. scribed 1/4

S18 BT. Placed 54-3s and brass washers stamped PLS 1051 on BTs. Painted blazes red and 6" red band around. Placed 54-4 on steel fence post 5' East of corner.

REGISTERED PROFESSIONAL LAND SURVEYOR

> OREGON OCT. 17. 1975 BARRY B. BARBOUR 1 0 5 1

I hereby certify that the above corner monument was reestablished as herein described.

Date Filed

File No. 789 - 84 R

Witnesses: Cecil O. Prophet Doris Grey

October 4, 1979

Office of County Surveyor County of Union State of Oregon I hereby certify that the within instrument was filed	
for record on the 6th day of December 1979.	UNION COUNTY SURVEYOR
Form R6-7100-57 (9/71)	Date Received