# CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## **History of Original Corner Establishment:**

The original corner was set by W.B. Barr, U.S. Deputy Surveyor, under Contract No. 388, dated May 7<sup>th</sup>, 1881.

The original notes state:

Marked basalt rock 12 x 8 x 6 for ½ sec corner. Raised mound of rock as per instructions.

Union County Survey No. 008-1994 states that this corner was searched for but not found. A 5/8" x 30" iron rod with a plastic cap marked D.L.T. & ASSOC., LS 1362 was set by single proportionate measure.

# DIAGRAM T 6 S R 38 E 1/4 S 15 S 22 PLS 1817 2006

## **Description of Corner Evidence Found:**

Found 5/8" rebar with yellow plastic cap marked "DLT ASSOC 1362" at a new fence corner. Fences run North and East from said corner. This position is not accepted as the South quarter corner of Section 15.

An extensive search was made for the basalt rock set by W.B. Barr, but the stone was not found, therefore the corner is deemed obliterated. I accept an old fence corner as the best local evidence of the location of the South quarter corner of Section 15. Fence remnants were retraced East from said fence corner for a half of a mile along the South line of the Southeast quarter of Section 15, and North from said fence corner for one mile along the North-South mid-section line of Section 15. These fences relate well with historic land ownership patterns for the area.

# Description of Monument and Accessories I Established to Perpetuate the Original Location of the Corner:

Set a  $2\frac{1}{2}$ " diameter brass cap, stamped as shown in the diagram above, on a 1" x 30" galvanized pipe, North of the fence post at the old North-East fence corner.


### **Corner Monument References:**

A 5/8" x 30" rebar with orange plastic cap marked "REFERENCE MONUMENT" bears N. 31° E., 4.64 feet, set flush with the ground.

A 5/8" x 30" rebar with orange plastic cap marked "REFERENCE MONUMENT" bears N.  $40^{\circ}$  W., 4.69 feet, set flush with the ground.

Reference monuments set with a staff compass and steel chain.

I, Thomas J. Hanley certify that this corner was properly reestablished by myself as witnessed by Kirby Danford on May 22, 2006.



REGISTERED PROFESSIONAL LAND SURVEYOR

Then J. Harley

OREGON
JULY 13, 1979
THOMAS J. HANLEY

Renews June 30, 2007

## HORIZONTAL CONTROL DATA

## UNION COUNTY, OREGON **OREGON STATE PLANE, NORTH ZONE (3601)**

STA NAME:

200927

QUARTER CORNER COMMON TO SECTIONS 15 AND 22

38 E.

TWP.

6 S RGE. GEODETIC COORD: NAD 83(91)

DATE TIED: September 29, 2009

LAT:

45 ° 2 ' 9.29643 " Ν

SURVEYOR: RICK ROBINSON

LONG:

2 ' 118°

38.75427 "

**OPLS 2219** 

FIRM: BAGETT, GRIFFITH, & BLACKMAN

SP. COOR: NAD 83(91)

2006 ADAMS AVENUE

LAGRANDE, OR 97850

N:

508836.586

INT FT.

(541) 963-6092

E:

8836841.774

INT FT.

TYPE: GPS

THETA:

1 ° 44'

30.1 "

ORDER: SECOND CLASS: 1

SCALE FACTOR:

0.9998972577

ELEV:

3964.4899

US FT.

ELEV: DATUM: NGVD 29

#### **COMMENTS:**

Corner is a 2 1/2" brass cap monument

Cap is marked as shown.

T6S R38E

S 15

1/4 -S 22

PLS 1817

2006

REGISTERED **PROFESSIONAL** LAND SURVEYOR

RICK G. ROBINSON 2219

Renewal Date: December 31, 2010

1 METER = 3.28083333333... US FEET = 39.37 INCHES

1 METER = 3.280839895 INT'L FEET OR 1 INCH = 2.54 CM

TO CALCULATE ELEVATION FACTOR (IN THE NORTH AMERICAN CONTINENT)

DIVIDE 20,906,000 BY (20,906,000 + ELLIPSOID ELEV. IN FEET)