


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

History of original corner establishment:

This corner was not established by a previous survey.



Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a USFS 3¼" aluminum capped monument, cap marked per diagram, 22" in the ground, with a mound of stone to cap, from which:

- A ½ " rebar, with a 1½" aluminum cap, stamped "LS 2058", bears N.41°41'E., 40.85'.
- A ½ " rebar, with a 1½" aluminum cap, stamped "LS 2058", bears S.41°15'E., 49.05'.
- A ½ " rebar, with a 1½" aluminum cap, stamped "LS 2058", bears S.42°47'W., 63.18'.
- A ½ " rebar, with a 1½" aluminum cap, stamped "LS 2058", bears N.59°53'W., 65.55'.

REFERENCE: RECORD OF SURVEY, LONGSHOT CADASTRAL SURVEY  
WITNESS TO MONUMENT: DAVID SUTHERLAND  
BEARINGS AND DISTANCES TAKEN TO THE CENTER OF CAP.  
BASIS OF BEARINGS WAS A GEODETIC BEARING DETERMINED FROM GPS OBSERVATIONS.

UNION COUNTY  
SURVEYOR

---

Date Received 10/28/98  
Date Filed 10/31/98  
By R. ROBINSON, DEPUTY  
File No. 115-1998R

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*M. J. Stoll* 10/98

OREGON  
JULY 15, 1983  
RONALD E. STOLL  
2058

Office of \_\_\_\_\_ County of \_\_\_\_\_  
State of \_\_\_\_\_ I hereby certify that the within instrument was filed in this office  
for record on the \_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_  
\_\_\_\_\_ by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)