CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

DIAGRAM T 6 S R 41 E N W 1/16

S 12

LS 2058 1994

Description of corner evidence found:

AQ

Description of monument and accessories I established to perpetuate the original location of this corner:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

A STATE OF THE PROPERTY OF THE PROPERTY

Set a USFS 3 1/4" aluminum capped pipe, cap marked per diagram, 26" in ground with small mound of stone to cap. Point falls 20' ± southerly E/W fence line and 175' ± westerly fence line to north.

A Fir, 7" diam., bears S.83°15'W., 39.2', scribed "NW1/16S12BT". A Pine, 10" diam., bears N.04°40'W., 33.3' scribed "NW1/16S12BT".

REFERENCE: RECORD OF SURVEY, LONGSHOT CADASTRAL SURVEY WITNESS TO MONUMENT: ERIC GREEN

BEARINGS TAKEN TO BRASS TAG AT CENTER OF BLAZE, DISTANCES MEASURED TO BRASS TAG ON SIDE CENTER OF TREE. OBSERVED WITH ELECTRONIC TOTAL STATION AND STEEL TAPE.

BASIS OF BEARINGS WAS A GEODETIC BEARING DETERMINED FROM GPS OBSERVATIONS.

| | | MONOUL COLLIER |
|-----------------------|---|--|
| Office of | County of | Mile in the same of the same o |
| State of | _ I hereby certify that the within instru | ment was filed in his office |
| for record on the day | of, 19 | Date Received 10 2018 |
| (COUNTY OFFIC | CIAL) by(DEPUTY) | Date Filed_10/31/98 |
| | | E. R. ROBINSON DEALTY |
| | | File No. 149 -1998 R |

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner originally established in 1994 by Ronald E. Stoll, PLS 2058, under U.S. Forest Service contract. Stoll's notes state:

Set a USFS 3 1/4" aluminum capped pipe, cap marked per diagram, 26" in ground with small mound of stone to cap. Point falls 20' +/- southerly E/W fence line and 175' +/- westerly fenceline to north.

A Fir, 7" diam., bears S83*15'W, 39.2', scribed: NW1/16 S12 BT. A Pine, 10" diam., bears N04*40'W, 33.3', scribed: NW1/16 S12 BT.

F-22

DIAGRAM

T6S R41E

NW 1/16

S12

LS 2058

1994

Typical USFS Cap

Description of corner evidence found:

A 3 1/4" USFS aluminum cap on aluminum pipe marked as shown in corner diagram 3" above ground.

From Which:

A Douglas Fir 8" in diameter bears S83°W (Record S83°15'W), 39.8' (Record 39.2') with visible scribing.

A Ponderosa Pine 11" in diameter bears N5°W (Record N04°40'W), 33.8' (Record 33.3') with visible scribing.

Steel fencepost with 54-2 and 54-9 signs bears west, 2.0'. Steel fencepost with 54-2 sign bears north, 2.2'.

Corner monument is south +/-25 of east—west fenceline.

Description of monument and accessories I established to perpetuate the original location of this corner:

Corner monument probably moved by Stoll after bearing trees were taken. Bearing tree scribes do not quite face corner monument. Remeasure bearings and distances to both bearing trees. Distances measured from Stoll's chaining nails.

Bearing trees have 54-3 and 54-9 signs and a 6" red painted band. The bearing tree faces are also painted red.

Date: November 21, 2007

Declination: 16°E

UNION COUNTY SURVEYOR

Date Received 12/1/07

Date Filed 12/11/07

Ly 43 7. Blen
No. 029 - 2007 R.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 19, 1994 KENNETH A. LIND 2672

Renews: 12-31-08