
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T6S R41 ER-24



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 029-2023

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position by survey, I set a 5/8"x30" iron pin 2 1/2" aluminum cap, marked as shown below, 28 inches in the ground, from which:

NEW BEARING OBJECTS:

A 5/8"x15" iron pin bears North 2°30' East, a distance of 15.89 feet, with 1 $\frac{1}{2}$ " aluminum cap marked BGB SURVEY MARKER N RP A 5/8"x15" iron pin bears South 87°30' West, a distance of 15.42 feet, with 1 $\frac{1}{2}$ " aluminum cap marked BGB SURVEY MARKER W RP

Corner falls approx. 30 ft. North of an fence corner from which fences run North, South and East. I hereby certify that the corner was monumented on November 16, 2023.

GRIFFITH & SLACAL S24
E 1/16 S25

OPLS 83571
2023

REGISTERED
PROFESSIONAL
LAND STRVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2025

I used a RTK GPS in the establishment of the accessories. Basis of Bearing is as per Survey Number 029-2023

UNION COUNTY
SURVEYOR

Date Received 11/16/23

Date Filed 11/16/23

File Number <u>060 - 2023R</u>

R-24