CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was originally established by W.B. BARR, U.S. Deputy Surveyor, under Contract No. 443, dated May 29, 1882. Surveyor General records state: Set a stone 12"X 10"X 5", eight inches in the ground. Stone was marked with a 1/4 on the North face for Sec. corner, from which:
A 14" pine bears N65°W-64 lks dist., scribed 1/4SBT. A 16" pine bears S21°W-181 lks dist., scribed 1/4SBT.

DIAGRAM T6S R42E s 7 1/4-----S 18 1993 PLS 1106

See Survey 052-1994

Description of corner evidence found:

None, except a 1928 location poster nailed to a tree. Poster indicates that it was located by compass and pacing.

Description of monument and accessories I established to perpetuate the original location of this corner:

At postion established by survey:

Set a $2\frac{1}{2}$ " X 30" aluminum pipe with a $2\frac{1}{2}$ " aluminum cap, 24" in ground and surrounded with a mound of earth and stone.

Attached sign 54-9 to steel fence post, set 3.0 feet East of monument.

New bearing trees established:

A 15" ponderosa pine bears N 28° E - 12.6 feet, scribed: 1/4S7BT. A 11" ponderosa pine bears S $46\frac{1}{2}$ ° E - 5.9 feet, scribed: 1/4S18BT. A 11" ponderosa pine bears S 8° W - 23.7 feet, scribed: 1/4S18BT.

9" douglas fir bears S 85° W - 22.3 feet, scribed 1/4S18BT.

New bearing trees have a brass washer stamped "PLS 1106" nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each bearing tree.

I hereby certify that the above corner monument was properly monumented to U.S.F.S standards by me on December 1, 1993.

Compass declination 18° East.

REGISTERED PROFESSIONAL LAND SURVEYOR OREGON JULY 22, 19 WILLIAM R. WELLS 1106

renews 12-31-94 Office of...... County of...... State of....... , I hereby certify that the within instrument was filed in this office (COUNTY OFFICIAL)

Form R6-7100-57 (9/71)

*GPO-591-971, 1988